





report date: 2024-03-29

## General information

Make	MAZDA
Model	5 FURANO
Colour	Red
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	187 g/km
CO2 label	1



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

## Entry 1

Date 2021-09-07

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



2021-06-23 10:02

MOT history

MOT #10

Advice

MOT expiry date	2024-06-29
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #12	2023-06-27 08:55
MOT test number	625322101965
Result	<b>✓</b> Passed
Next expiry date	2024-06-29
Advice Offside Front Suspension arm pin or bush worn but not resulting in ex (i))	xcessive movement (5.3.4 (a)

MOT #11	2022-06-20 09:32
MOT test number	821943539749
Result	<b>✓</b> Passed
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT test	number	328876237691
Result		✓ Passed
MOT #9		2020-06-30 15:47
MOT test	number	649293252235
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2019-04-24 13:02

**MOT test number** 392452710755

**Result** ✓ Passed

MOT #7 2018-04-30 15:01

MOT test number 760389278309

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit Badly worn on inside shoulder. (4.1.E.1)

MOT #6 2018-04-30 10:46

**MOT test number** 111667604574

**Result** X Failed

**Advice** Offside Rear Tyre worn close to the legal limit Badly worn on inside shoulder. (4.1.E.1)

Fail Rear registration plate deteriorated (6.3.1d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #5 2017-05-10 11:32

**MOT test number** 377783730269

Result 

Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2016-05-10 08:48

**MOT test number** 513342841672

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR BUSH (2.4.G.2)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement REAR BUSH (2.4.G.2)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2015-05-13 12:18

**MOT test number** 225793535168

**MOT #2** 2014-05-07 13:29

**MOT test number** 237297624165

Result 

Passed

MOT #1 2013-05-23 12:07

**MOT test number** 807243943194

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-05-29
Last registration	2023-06-27
Complete history	See info



Registration #1	2010-05-29	24 mi
Registration #2	2013-05-23	31.663 mi
Registration #3	2014-05-07	40.326 mi
Registration #4	2015-05-13	50.402 mi
Registration #5	2016-05-10	59.611 mi
Registration #6	2017-05-10	70.266 mi
Registration #7	2018-04-30	81.135 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		0.00 44
Registration #13		
Registration #15		

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1410 kg
Max. allowed weight	2125 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	LF 10895894

CarCheck.co.uk page 12/12