



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA SXI 16V TWINPORT
Colour	Red
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-23
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-20
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	46
Total items failed	3

MOT #18	2023-08-21 12:41
MOT test number	173420624234
Result	✓ Passed
Next expiry date	2024-08-20
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-08-02 11:55
MOT test number	585016572487
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Coil spring corroded both coils (5.3.1 (b) (i))

**MOT #16**

2022-07-28 10:33

MOT test number

779220834620

Result**✗ Failed**

- Advice** Rear Coil spring corroded both coils (5.3.1 (b) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Windscreen washer not working (3.5 (a))
- DANGEROUS** Offside Front Tyre has ply or cords exposed 185/60/r15 84h (5.2.3 (d) (ii))
- MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Nearside Front Tyre(s) with different aspect ratios are fitted on the same axle. and has a nail in it (5.2.3 (b))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Windscreen wiper blade defective both wipers split and possibly wouldn't clear the screen (3.4 (b) (i))

MOT #15

2021-08-09 13:51

MOT test number

587291860310

Result**✓ Passed**

- Advice** Both front inner Tyres

**MOT #14**

2020-07-09 09:37

MOT test number

264272154553

Result

✓ Passed

Advice Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2020-07-08 08:45

MOT test number

645121667127

Result

✗ Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Front Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2019-05-13 12:26

MOT test number

685807251163

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2019-04-30 12:53**MOT test number** 820487951457**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #10** 2018-05-02 15:06**MOT test number** 562833817980**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Oil leak**MOT #9** 2018-04-25 13:03**MOT test number** 365116851132**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Brake cable has wires broken and is significantly weakened (3.5.1b)**Advice** Oil leak**MOT #8** 2017-04-10 09:07**MOT test number** 754819808570**Result** ✓ Passed**Advice** Corrosion to fuel filter**Advice** Slight blow from exhaust

**MOT #7** 2016-04-13 08:12**MOT test number** 900485956493**Result** ✓ Passed**Advice** Exhaust blow**Advice** Oil leak**MOT #6** 2015-04-17 09:03**MOT test number** 755617305133**Result** ✓ Passed**MOT #5** 2015-04-16 13:47**MOT test number** 195036405146**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #4** 2014-04-29 14:37**MOT test number** 849309714184**Result** ✓ Passed**MOT #3** 2013-10-08 09:16**MOT test number** 618111883227**Result** ✓ Passed**MOT #2** 2012-09-25 13:00**MOT test number** 396039162449**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake pads on limit**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2011-10-04 12:24
MOT test number	819437371267
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YR58TSY
Plate since	2019-03-28
Current registration	YR58TSY
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-30
Last registration	2023-08-21
Complete history	See info



Registration #1	2008-09-30	7 mi
Registration #2	2011-10-04	17.471 mi
Registration #3	2012-09-25	22.601 mi
Registration #4	2013-10-08	27.620 mi
Registration #5	2014-04-29	30.129 mi
Registration #6	2015-04-16	33.536 mi
Registration #7	2015-04-17	33.541 mi
Registration #8	2016-04-13	36.720 mi
Registration #9	2017-04-10	38.655 mi
Registration #10	2018-04-25	41.232 mi
Registration #11	2019-05-20	45.000 mi
Registration #12	2019-05-20	45.000 mi
Registration #13	2019-05-20	45.000 mi
Registration #14	2019-05-20	45.000 mi
Registration #15	2019-05-20	45.000 mi
Registration #16	2019-05-20	45.000 mi
Registration #17	2019-05-20	45.000 mi
Registration #18	2019-05-20	45.000 mi
Registration #19	2019-05-20	45.000 mi
Registration #20	2019-05-20	45.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1753 mm
Height	1413 mm
Length	4288 mm
Wheel base	2614 mm
Kerb weight	1180 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	19PU0404