



report date: 2024-03-29

General information

Make	FIAT
Model	QUBO DYNAMIC
Colour	Black
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	16.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 2.600 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-29
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-29
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #16 2023-10-30 12:06

MOT test number 593610938363

Result ✓ Passed

Next expiry date 2024-10-29

Advice Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-10-05 11:20

MOT test number 495459308335

Result ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2021-10-12 13:58

MOT test number 672797438081

Result ✓ Passed

**MOT #13** 2021-10-11 08:40**MOT test number** 432918922668**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))**Advice** Nearside Rear Nail in tyre**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2020-12-23 09:41**MOT test number** 704319398983**Result** ✓ Passed**MOT #11** 2020-01-03 09:31**MOT test number** 105102251063**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear exhaust hanger corroded**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-01-04 09:50**MOT test number** 738668547507**Result** ✓ Passed**MOT #9** 2018-01-05 09:26**MOT test number** 367809621347**Result** ✓ Passed

**MOT #8** 2017-01-06 15:25**MOT test number** 920204758456**Result** ✓ Passed**MOT #7** 2017-01-06 12:24**MOT test number** 951345120431**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #6** 2016-01-04 10:25**MOT test number** 735358529496**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front tyre worn on inner edge**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-12-30 11:27**MOT test number** 120287536840**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front tyre worn on inner edge**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #4** 2014-12-30 11:37**MOT test number** 637164864377**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-12-13 14:00**MOT test number** 795227843313**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #2** 2012-12-27 14:53**MOT test number** 416382462497**Result** ✓ Passed**MOT #1** 2011-11-08 16:00**MOT test number** 319192411360**Result** ✓ Passed**Notice** Front tyres worn on inner edges



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-30
Last registration	2023-10-30
Complete history	See info



Registration #1	2009-03-30	15 mi
Registration #2	2011-11-08	7.931 mi
Registration #3	2012-12-27	10.201 mi
Registration #4	2013-12-13	10.865 mi
Registration #5	2014-12-30	13.147 mi
Registration #6	2015-12-30	16.122 mi
Registration #7	2016-01-04	16.122 mi
Registration #8	2017-01-06	19.787 mi
Registration #9	2017-01-06	19.788 mi
Registration #10	2018-01-06	20.201 mi
Registration #11	2018-01-06	20.201 mi
Registration #12	2018-01-06	20.201 mi
Registration #13	2018-01-06	20.201 mi
Registration #14	2018-01-06	20.201 mi
Registration #15	2018-01-06	20.201 mi
Registration #16	2018-01-06	20.201 mi
Registration #17	2018-01-06	20.201 mi
Registration #18	2018-01-06	20.201 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	5924630