



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | FORD |
| Model | FOCUS ZETEC |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 126 mph |
| 0 - 60 mph | 9.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 134 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 144 g/km |
| CO2 label | F |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-09 |
| Pictures | 12 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-31 |
| MOT pass rate | 79 % |
| MOT passed | 11 |
| Failed MOT tests | 3 |
| Total advice items | 25 |
| Total items failed | 7 |

| | |
|------------------|--|
| MOT #14 | 2023-07-24 09:37 |
| MOT test number | 499545151540 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-31 |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|-----------------|---|
| MOT #13 | 2023-07-21 11:48 |
| MOT test number | 710541364641 |
| Result | ✗ Failed |
| Fail | Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |
| Fail | Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Fail | Nearside Front Headlamp aim projected beam image is obviously incorrect Bulb not securely fitted (4.1.2 (c)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|-----------------|---|
| MOT #12 | 2022-08-01 11:45 |
| MOT test number | 542735134323 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

**MOT #11**

2022-07-20 10:52

MOT test number

428547624251

Result

✗ Failed

- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #10

2021-07-06 09:39

MOT test number

336793565065

Result

✓ Passed

MOT #9

2020-08-06 11:48

MOT test number

665231964396

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))

MOT #8

2019-07-31 08:51

MOT test number

848778255552

Result

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Inner tread worn
- Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords tread (5.2.3 (d) (i))
- Advice** Nearside Rear Outer tread worn

**MOT #7** 2018-08-03 08:50**MOT test number** 486941763736**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #6** 2017-08-08 08:43**MOT test number** 318311111633**Result** ✓ Passed**Advice** Offside Front Inner tread worn**MOT #5** 2016-08-22 09:57**MOT test number** 564555491769**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-07-10 10:25**MOT test number** 555181195161**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Offside rear tyre has cut in tread**MOT #3** 2014-07-15 11:14**MOT test number** 286096594171**Result** ✓ Passed**Notice** Nearside rear indicator starting to show white light.



| | |
|-----------------|---|
| MOT #2 | 2014-07-15 10:01 |
| MOT test number | 398696694127 |
| Result | ✗ Failed |
| Fail | Offside Side repeater not working (1.4.A.2c) |
| Notice | Nearside rear indicator starting to show white light. |

| | |
|-----------------|--|
| MOT #1 | 2013-07-19 12:20 |
| MOT test number | 397180403405 |
| Result | ✓ Passed |
| Notice | Under-trays fitted obscuring some underside components |
| Notice | Child seat fitted not allowing full inspection of adult belt |
| Notice | Engine covers fitted obscuring some components in the engine bay |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
31 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 31 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2023-03-29 |
| Current registration | ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2010-07-16 |
| Last registration | 2023-07-24 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-07-16 | 24 mi |
| Registration #2 | 2013-07-19 | 20.198 mi |
| Registration #3 | 2014-07-15 | 23.441 mi |
| Registration #4 | 2014-07-15 | 23.441 mi |
| Registration #5 | 2015-07-10 | 27.787 mi |
| Registration #6 | 2016-08-22 | 42.721 mi |
| Registration #7 | 2017-08-08 | 50.261 mi |
| Registration #8 | 2018-08-03 | 53.201 mi |
| Registration #9 | 2019-08-03 | 55.201 mi |
| Registration #10 | 2020-08-03 | 57.201 mi |
| Registration #11 | 2021-08-03 | 59.201 mi |
| Registration #12 | 2022-08-03 | 61.201 mi |
| Registration #13 | 2023-08-03 | 63.201 mi |
| Registration #14 | 2024-08-03 | 65.201 mi |
| Registration #15 | 2025-08-03 | 67.201 mi |
| Registration #16 | 2026-08-03 | 69.201 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1991 mm |
| Height | 1447 mm |
| Length | 4342 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1461 kg |
| Max. allowed weight | 1950 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|---------------|---------|
| Engine number | 9E49991 |
|---------------|---------|