




report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Silver
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-05
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	40
Total items failed	4

MOT #16	2023-06-06 13:49
MOT test number	542716664416
Result	✓ Passed
Next expiry date	2024-06-05
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2023-05-26 08:24
MOT test number	803884940895
Result	✗ Failed
DANGEROUS	Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
MAJOR	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
MAJOR	Service brake efficiency below requirements (1.2.2 (a) (i))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #14 2022-09-24 14:14

MOT test number 137480254497

Result ✔ Passed

- Advice** Centre exhaust flange to dpf section securing device heavily corroded
- Advice** Rear Exhaust has a minor leak of exhaust gases pipe into silencer starting to split (6.1.2 (a))

MOT #13 2022-09-23 10:14

MOT test number 125419118123

Result ✘ Failed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Exhaust mounting defective Studs and nuts at DPF rear flange severely corroded. (6.1.2 (a))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #12 2022-09-17 17:31

MOT test number 422084119117

Result ✘ Failed

- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Exhaust mounting defective Studs and nuts at DPF rear flange severely corroded. (6.1.2 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #11 2021-09-15 08:19

MOT test number 361083091407

Result ✓ Passed

Advice Play in steering rack inner joint(s)

MOT #10 2020-09-17 14:14

MOT test number 576296508433

Result ✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to split (5.3.4 (a) (i))

Advice Brake pipe corroded, covered in grease or other material all pipes covered in plastic unable to fully inspect (1.1.11 (c))

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Under trays fitted unable to fully inspect

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to split (5.3.4 (a) (i))

MOT #9 2020-09-17 14:14

MOT test number 918383428480

Result ✗ Failed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to split (5.3.4 (a) (i))

Advice Brake pipe corroded, covered in grease or other material all pipes covered in plastic unable to fully inspect (1.1.11 (c))

Advice Under trays fitted unable to fully inspect

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to split (5.3.4 (a) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #8 2019-09-20 13:58

MOT test number 747555573297

Result ✔ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bushes going soft (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bushes going soft (5.3.4 (a) (i))

MOT #7 2019-09-18 14:55

MOT test number 918458595792

Result ✘ Failed

MAJOR Offside Rear Seat belt buckle not functioning as intended outer middle row does not catch (7.1.2 (d))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bushes going soft (5.3.4 (a) (i))

MAJOR Fuel system component leaking from tank area (6.1.3 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bushes going soft (5.3.4 (a) (i))

MOT #6 2018-01-25 15:04

MOT test number 274305554074

Result ✔ Passed

MOT #5 2018-01-25 15:04

MOT test number 720037639827

Result ✘ Failed

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #4 2016-11-29 12:31

MOT test number 445022418844

Result ✔ Passed



MOT #3	2015-11-30 14:06
MOT test number	553235669923
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2015-11-27 09:22
MOT test number	808119126491
Result	✗ Failed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2014-11-10 12:03
MOT test number	469384214416
Result	✓ Passed
Notice	Both front tyres worn slightly on inner and outer edge



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
5 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KM61CZK
Plate since	2024-03-28
Current registration	KM61CZK
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-09
Last registration	2023-06-06
Complete history	See info



Registration #1	2011-12-09	25 mi
Registration #2	2014-11-10	59.454 mi
Registration #3	2015-11-27	73.980 mi
Registration #4	2015-11-30	73.982 mi
Registration #5	2016-11-29	83.926 mi
Registration #6	2018-01-25	98.558 mi
Registration #7	2018-01-25	98.558 mi
Registration #8	2019-09-18	118.112 mi
Registration #9	2019-09-20	118.118 mi
Registration #10	2019-09-20	118.118 mi
Registration #11	2019-09-20	118.118 mi
Registration #12	2019-09-20	118.118 mi
Registration #13	2019-09-20	118.118 mi
Registration #14	2019-09-20	118.118 mi
Registration #15	2019-09-20	118.118 mi
Registration #16	2019-09-20	118.118 mi
Registration #17	2019-09-20	118.118 mi
Registration #18	2019-09-20	118.118 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1044305