



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Red
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-16
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2023-02-16 16:00
MOT test number	629754992098
Result	✓ Passed
Next expiry date	2024-03-07
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material ALL CORRODED (1.1.11 (c))

MOT #17	2023-02-16 16:00
MOT test number	825903063655
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Brake pad(s) less than 1.5 mm thick Both rear (1.1.13 (a) (ii))
Advice	Brake pipe corroded, covered in grease or other material ALL CORRODED (1.1.11 (c))

MOT #16	2022-02-12 16:06
MOT test number	986585111921
Result	✓ Passed
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Both front to rear brake pipes covered in grease unable to carry out full inspection

**MOT #15**

2022-02-09 11:13

MOT test number

154879262110

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**Pass with rectification** Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))**MOT #14**

2021-03-02 13:57

MOT test number

757444884919

Result**✓ Passed****MOT #13**

2021-02-23 09:25

MOT test number

237207739471

Result**✗ Failed****Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Emissions not tested exhaust leak (8.2.1.2 (d))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))**Advice** Nearside parking brake effort low**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #12**

2020-02-18 09:17

MOT test number

470892146948

Result**✓ Passed**

**MOT #11** 2019-02-19 09:16**MOT test number** 894671715345**Result** ✓ Passed**MOT #10** 2019-02-19 09:16**MOT test number** 627707783535**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2018-02-13 09:54**MOT test number** 680077309215**Result** ✓ Passed**MOT #8** 2018-02-13 09:54**MOT test number** 236901886252**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Driver's door cannot be opened from inside the vehicle (6.2.B.1b)**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2017-02-14 09:36**MOT test number** 421154916191**Result** ✓ Passed**MOT #6** 2016-03-01 13:28**MOT test number** 349676880393**Result** ✓ Passed**Advice** Nearside Rear TYRE HAS A NAIL IN TREAD PATTERN.



MOT #5	2015-02-17 10:10
MOT test number	655858645071
Result	✓ Passed
MOT #4	2014-02-27 12:53
MOT test number	846748854008
Result	✓ Passed
MOT #3	2013-02-20 09:16
MOT test number	456201353090
Result	✓ Passed
MOT #2	2012-02-23 09:50
MOT test number	227334852062
Result	✓ Passed
MOT #1	2011-02-25 10:26
MOT test number	195606251463
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 AK08MBF
Plate since	2019-09-29
Current registration	 AK08MBF
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-07
Last registration	2023-02-16
Complete history	See info



Registration #1	2008-03-07	26 mi
Registration #2	2011-02-25	30.322 mi
Registration #3	2012-02-23	36.318 mi
Registration #4	2013-02-20	42.672 mi
Registration #5	2014-02-27	48.620 mi
Registration #6	2015-02-17	52.979 mi
Registration #7	2016-03-01	57.154 mi
Registration #8	2017-02-14	65.135 mi
Registration #9	2018-02-13	72.764 mi
Registration #10	2018-02-13	72.764 mi
Registration #11	2019-02-20	75.277 mi
Registration #12	2019-02-20	75.277 mi
Registration #13	2019-02-20	75.277 mi
Registration #14	2019-02-20	75.277 mi
Registration #15	2019-02-20	75.277 mi
Registration #16	2019-02-20	75.277 mi
Registration #17	2019-02-20	75.277 mi
Registration #18	2019-02-20	75.277 mi
Registration #19	2019-02-20	75.277 mi
Registration #20	2019-02-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564