



report date: 2024-03-28

General information

Make	MAZDA
Model	5 FURANO LIMITED EDITION
Colour	Black
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.4 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-11
Pictures	29
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #18** 2022-05-05 15:33**MOT test number** 803323563135**Result** ✓ Passed**Next expiry date** 2023-05-25

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm and BALD Inner edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17 2022-04-26 11:22**MOT test number** 229013885415**Result** ✗ Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail Nearside Rear Suspension arm pin or bush likely to become detached Trailing arm front bush (5.3.4 (a) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm and BALD Inner edge (5.2.3 (e))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail Offside Rear Suspension arm pin or bush likely to become detached Trailing arm front bush (5.3.4 (a) (ii))

**MOT #16**

2021-04-26 09:36

MOT test number

239008762605

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Fuel tank heat shield insecure
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner edge (worn unevenly) (5.2.3 (e))
- Advice** Rear fog lamp slightly loose
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Central Rear seat not fitted at time of test

MOT #15

2020-05-26 08:45

MOT test number

694379090856

Result

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2019-03-18 15:48

MOT test number

855217422246

Result

✓ Passed

MOT #13

2018-03-29 07:58

MOT test number

736346740383

Result

✓ Passed

- Advice** N/s headlamp dim/bulb possibly inserted incorrectly

**MOT #12** 2018-03-20 14:59**MOT test number** 368259635461**Result** ✗ Failed**Advice** N/s headlamp dim/bulb possibly inserted incorrectly**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #11** 2017-03-18 10:06**MOT test number** 142362254685**Result** ✓ Passed**Advice** Offside Rear tyre inner edge bald**MOT #10** 2017-03-17 16:05**MOT test number** 893580107773**Result** ✗ Failed**Advice** Offside Rear tyre inner edge bald**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Rear fog lamp not working (1.3.2b)**MOT #9** 2016-03-07 16:48**MOT test number** 310499291415**Result** ✓ Passed**MOT #8** 2015-03-06 16:31**MOT test number** 177285265063**Result** ✓ Passed

**MOT #7** 2014-04-03 13:17**MOT test number** 646203794065**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-04-03 13:17**MOT test number** 996073894023**Result** ✗ Failed**Pass with rectification** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-07-05 12:32**MOT test number** 447726283148**Result** ✓ Passed**MOT #4** 2012-07-02 11:20**MOT test number** 485574182152**Result** ✓ Passed**MOT #3** 2011-07-23 10:35**MOT test number** 249824801215**Result** ✓ Passed**MOT #2** 2010-07-27 15:34**MOT test number** 622908800298**Result** ✓ Passed**MOT #1** 2009-09-28 11:56**MOT test number** 131581679245**Result** ✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	ML56GDO
Plate since	2019-09-28
Current registration	ML56GDO
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-28
Last registration	2022-05-05
Complete history	See info



Registration #1	2006-09-28	9 mi
Registration #2	2009-09-28	19.217 mi
Registration #3	2010-07-27	24.306 mi
Registration #4	2011-07-23	32.305 mi
Registration #5	2012-07-02	39.114 mi
Registration #6	2014-04-03	47.792 mi
Registration #7	2015-03-06	61.673 mi
Registration #8	2016-03-07	74.754 mi
Registration #9	2017-03-17	85.308 mi
Registration #10	2018-03-20	95.357 mi
Registration #11	2019-03-20	105.357 mi
Registration #12	2020-03-20	115.357 mi
Registration #13	2021-03-20	125.357 mi
Registration #14	2022-03-20	135.357 mi
Registration #15	2023-03-20	145.357 mi
Registration #16	2024-03-20	155.357 mi
Registration #17	2025-03-20	165.357 mi
Registration #18	2026-03-20	175.357 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Max. allowed weight	2100 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Engine number	LF 162759