




report date: 2024-03-29

General information

Make	VOLVO
Model	S40 T5 SE SPORT V50
Colour	Black
Year of manufacture	2008
Top speed	146 mph
0 - 60 mph	6.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	230 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	29.7 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2024-05-30
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	37
Total items failed	8

MOT #17 2023-05-17 18:14**MOT test number** 546538158724**Result** Passed**Next expiry date** 2024-05-30

- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Lower Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))

MOT #16 2022-05-31 08:28**MOT test number** 530873938671**Result** Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #15 2021-05-24 12:16**MOT test number** 503147427258**Result** Passed

**MOT #14** 2020-03-25 09:10**MOT test number** 535089970822**Result** ✓ Passed**MOT #13** 2019-03-28 17:16**MOT test number** 354225255333**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Nearside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**MOT #12** 2019-03-27 11:01**MOT test number** 446164698792**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #11** 2018-05-15 13:42**MOT test number** 175622140789**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Several small chips in windscreen**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #10**

2017-05-22 10:46

MOT test number

793851750423

Result

✓ Passed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear tyre side wall splitting
- Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #9

2016-05-17 09:55

MOT test number

944230381154

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8

2015-05-19 12:17

MOT test number

459429735147

Result

✓ Passed

**MOT #7** 2015-05-15 09:35**MOT test number** 586645435158**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #6** 2014-05-15 16:15**MOT test number** 628335834107**Result** ✓ Passed**MOT #5** 2014-05-13 10:43**MOT test number** 246663534443**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Road wheel cracked (4.2.A.1a)**MOT #4** 2013-05-13 14:37**MOT test number** 198053233161**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-05-05 09:48**MOT test number** 745796622105**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Chip in screen



MOT #2	2012-05-05 09:48
MOT test number	448746122181
Result	✗ Failed
Notice	Chip in screen
Pass with rectification	Nearside Side repeater not working (1.4.A.2c)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2011-05-07 14:57
MOT test number	236767621455
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	30 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-28
Last registration	2023-05-17
Complete history	See info



Registration #1	2008-04-28	15 mi
Registration #2	2011-05-07	45.581 mi
Registration #3	2012-05-05	62.429 mi
Registration #4	2013-05-13	71.953 mi
Registration #5	2014-05-13	76.738 mi
Registration #6	2014-05-15	76.747 mi
Registration #7	2015-05-15	78.994 mi
Registration #8	2015-05-19	79.004 mi
Registration #9	2016-05-17	79.553 mi
Registration #10	2016-05-20	80.000 mi
Registration #11	2016-05-20	80.000 mi
Registration #12	2016-05-20	80.000 mi
Registration #13	2016-05-20	80.000 mi
Registration #14	2016-05-20	80.000 mi
Registration #15	2016-05-20	80.000 mi
Registration #16	2016-05-20	80.000 mi
Registration #17	2016-05-20	80.000 mi
Registration #18	2016-05-20	80.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1526 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4310816