



report date: 2024-03-29

General information

Make	VAUXHALL
Model	CASCADA SE S/S
Colour	Grey
Year of manufacture	2014
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	140 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.362 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1	
Date	2021-12-08
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-01
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	1

MOT #11	2024-03-02 14:13
MOT test number	408273074375
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-02-28 12:50
MOT test number	156701261539
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9	2022-02-28 15:45
MOT test number	350577831025
Result	✓ Passed

MOT #8	2022-02-25 13:27
MOT test number	584619117189
Result	✗ Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Minor	Offside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #7** 2021-02-13 10:25**MOT test number** 308060359187**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases front flexi pipe (6.1.2 (a))**MOT #6** 2020-02-05 11:23**MOT test number** 758544533130**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-02-20 16:14**MOT test number** 124911270210**Result** ✓ Passed**Advice** Oil leak**Advice** Front brake discs worn**MOT #4** 2019-01-29 12:05**MOT test number** 814990028548**Result** ✗ Failed**Advice** Oil leak**Advice** Front brake discs worn**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #3** 2018-02-02 09:08**MOT test number** 201907369816**Result** ✓ Passed



MOT #2	2017-01-26 11:38
MOT test number	151662926981
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2017-01-26 11:38
MOT test number	835259777960
Result	✗ Failed
Pass with rectification	Nearside Side repeater insecure (1.4.A.2b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LY63MXS
Plate since	2019-03-29
Current registration	 LY63MXS
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-15
Last registration	2024-03-02
Complete history	See info



Registration #1	2014-01-15	22 mi
Registration #2	2017-01-26	23.575 mi
Registration #3	2017-01-26	23.575 mi
Registration #4	2018-02-02	30.089 mi
Registration #5	2019-01-29	37.149 mi
Registration #6	2019-02-20	37.427 mi
Registration #7	2020-02-05	44.495 mi
Registration #8	2020-03-20	51.577 mi
Registration #9	2020-03-20	51.577 mi
Registration #10	2020-03-20	51.577 mi
Registration #11	2020-03-20	51.577 mi
Registration #12	2020-03-20	51.577 mi
Registration #13	2020-03-20	51.577 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1626 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	A14NET -19CH7421LUJ