



report date: 2024-03-28

## General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE DUALOGIC
Colour	White
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B








Internet history

Entry 1

Date	2022-02-21
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-03-16
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	53
Total items failed	7

MOT #13 2024-02-29 08:35

MOT test number 923190050500

Result ✓ Passed

Next expiry date 2025-03-16

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 2mm and bold on inner shoulder (STRONG ADVISE) (5.2.3 (e))

**Advice** Offside Front Play in steering rack inner joint(s)

**Advice** Tyre worn close to legal limit/worn on edge Both rears (5.2.3 (e))

MOT #12 2023-03-17 16:47

MOT test number 394315354966

Result ✓ Passed

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Parking brake efficiency uneven. nearside low

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement bearings worn (5.3.4 (a) (i))

**Advice** Dash warning lights glowing dim

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #11**

2023-03-17 09:18

**MOT test number**

153031652697

**Result****✗ Failed****Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Parking brake efficiency uneven. nearside low**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement bearings worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #10**

2022-03-16 10:48

**MOT test number**

600686329693

**Result****✓ Passed****MOT #9**

2021-10-13 09:23

**MOT test number**

956917518829

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges worn (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge edges worn (5.2.3 (e))

**MOT #8** 2020-10-15 14:58**MOT test number** 601011809666**Result** ✓ Passed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #7** 2020-10-15 09:01**MOT test number** 578740925731**Result** ✗ Failed

- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Bald on edge. (5.2.3 (e))
- Fail** Nearside Windscreen wiper not working (3.4 (a))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #6**

2019-10-08 15:09

**MOT test number**

956848867500

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Engine cover fitted obscuring components.
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Bonnet hinge distorted.

**MOT #5**

2019-10-08 09:22

**MOT test number**

559140701073

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Engine cover fitted obscuring components.
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Bonnet hinge distorted.
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Worn to metal. (1.1.14 (a) (ii))

**MOT #4** 2018-10-11 13:48**MOT test number** 226154362492**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on edge (5.2.3 (e))**MOT #3** 2018-10-10 13:25**MOT test number** 873741804446**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on edge (5.2.3 (e))**Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #2** 2017-10-03 10:52**MOT test number** 246555482283**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #1** 2016-10-20 15:30**MOT test number** 471938939254**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
16 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	16 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-24
Last registration	2024-02-29
Complete history	<a href="#">See info</a>



Registration #1	2013-10-24	12 mi
Registration #2	2016-10-20	22.653 mi
Registration #3	2017-10-03	30.257 mi
Registration #4	2018-10-10	37.573 mi
Registration #5	2018-10-11	37.574 mi
Registration #6	2019-10-08	46.565 mi
Registration #7	2019-10-08	46.565 mi
Registration #8	2020-10-15	52.002 mi
Registration #9	2020-10-15	52.002 mi
Registration #10	2020-10-15	52.002 mi
Registration #11	2020-10-15	52.002 mi
Registration #12	2020-10-15	52.002 mi
Registration #13	2020-10-15	52.002 mi
Registration #14	2020-10-15	52.002 mi
Registration #15	2020-10-15	52.002 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4978905