





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE T
Colour	Silver
Year of manufacture	2003
Top speed	126 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	298 Nm at 2.000 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1


Date 2021-07-14

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2022-05-21
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #19	2021-05-22 07:44
MOT test number	778252270477
Result	✓ Passed
Next expiry date	2022-05-21

MOT #18	2020-07-06 09:39
MOT test number	843247207355
Result	✓ Passed
Advice Central Exhaust mounting defective (6.1.2 (a))	

MOT #17	2019-03-28 10:48
MOT test number	771405524320
Result	✓ Passed
MOT #16	2018-03-15 09:34
MOT test number	592906871827
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Pass with rectification

Offside Front Direction indicators incorrect colour (1.4.A.2f)

Pass with rectification

Nearside Front Direction indicators incorrect colour (1.4.A.2f)

MOT #14 2017-03-27 08:52 **MOT** test number 102440521911 Result ✓ Passed **MOT #13** 2017-03-27 08:52 **MOT test number** 653992116989 Result × Failed **Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #12	2016-03-31 08:52
MOT test number	770855824572
Result	✓ Passed
MOT #11	2016-03-31 08:52
MOT test number	703938582418
Result	▼ Failed
Pass with rectification	Nearside Front Headlamp aim too high and too far to the left. (1.8)

MOT #10	2015-04-02 11:53
MOT test number	105762495069
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

 MOT #9
 2014-04-03 11:11

 MOT test number
 605623994002

 Result
 ✓ Passed

 MOT #8
 2013-04-02 10:21

 MOT test number
 145112793047

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (3.5.1g)

MOT #7

MOT test number

859179982022

Result

✓ Passed

MOT #6 2011-03-03 11:40 **MOT** test number 116752661061 Result Passed **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) **Notice** Child seat fitted not allowing full inspection of adult belt Notice N/s/r tyre cracking inside it's tread pattern Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c) Notice Front brake discs lipped

 MOT #5
 2010-03-08 15:35

 MOT test number
 172437860435

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

MOT test number

Result

MOT #2

MOT test number

2007-03-28 10:21

MOT test number

481267687092

Result

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT test number

Passed

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2

Date

_

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK ZIN
Plate since	
Current registration	NK.
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-03-31
Last registration	2021-05-22
Complete history	See info



Registration #1	2003-03-31	24 mi
Registration #2	2006-03-25	35.915 mi
Registration #3	2007-03-28	40.485 mi
Registration #4	2008-03-28	46.214 mi
Registration #5	2009-03-06	627.655 mi
Registration #6	2010-03-08	53.358 mi
Registration #7	2011-03-03	55.886 mi
Registration #8	2012-03-29	60.082 mi
Registration #9	2013-04-02	64.914 mi
Registration #10	2014-04-03	70.060 mi
Registration #11	2015-04-02	74.379 mi
Registration #12		71.777 es
Registration #13		11.700 mg
Registration #14		71.777 es
Registration #15		11.777 mi
Registration #16		71.777 es
Registration #17		11.700 mg
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

CarCheck.co.uk page 12/12

Engine number AWU707834