



**HN58PXD**


report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI VTR PLUS EGS GRAND PICASSO
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-03-30
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	7
Total items failed	8

MOT #17	2024-03-22 12:28
MOT test number	538420276137
Result	✓ Passed
Next expiry date	2025-03-30
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-03-31 09:18
MOT test number	352693534866
Result	✓ Passed
Minor	Nearside Obligatory mirror slightly loose mirror glass (3.3 (b) (i))
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2022-02-14 10:57
MOT test number	957868543522
Result	✓ Passed

MOT #14	2021-01-19 09:56
MOT test number	568441442655
Result	✓ Passed

**MOT #13** 2020-02-13 10:31**MOT test number** 793492351049**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2019-01-29 10:59**MOT test number** 302364614546**Result** ✓ Passed**MOT #11** 2018-02-06 16:42**MOT test number** 391986861360**Result** ✓ Passed**MOT #10** 2018-02-06 15:11**MOT test number** 954513447240**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**MOT #9** 2017-01-25 09:36**MOT test number** 617839650285**Result** ✓ Passed**MOT #8** 2016-02-15 17:47**MOT test number** 356803835319**Result** ✓ Passed**Advice** Undertrays fitted

**MOT #7** 2016-02-15 10:50**MOT test number** 326397728937**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake lever insecure (3.1.3b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Undertrays fitted**MOT #6** 2015-01-16 12:51**MOT test number** 295846815046**Result** ✓ Passed**MOT #5** 2015-01-16 12:51**MOT test number** 829666415087**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2014-01-22 17:00**MOT test number** 898462624030**Result** ✓ Passed**MOT #3** 2014-01-22 11:01**MOT test number** 148282424021**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2012-12-03 09:59
MOT test number	885058132336
Result	✓ Passed

MOT #1	2011-11-15 08:26
MOT test number	728239911390
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
30 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	30 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>HN58PXD</b>
Plate since	2019-09-28
Current registration	<b>HN58PXD</b>
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-26
Last registration	2024-03-22
Complete history	<a href="#">See info</a>



Registration #1	2008-11-26	20 mi
Registration #2	2011-11-15	33.095 mi
Registration #3	2012-12-03	40.280 mi
Registration #4	2014-01-22	47.344 mi
Registration #5	2014-01-22	47.344 mi
Registration #6	2015-01-16	52.727 mi
Registration #7	2016-02-15	58.543 mi
Registration #8	2016-02-15	58.543 mi
Registration #9	2017-01-25	61.627 mi
Registration #10	2018-01-22	65.317 mi
Registration #11	2018-01-22	65.317 mi
Registration #12	2018-01-22	65.317 mi
Registration #13	2018-01-22	65.317 mi
Registration #14	2018-01-22	65.317 mi
Registration #15	2018-01-22	65.317 mi
Registration #16	2018-01-22	65.317 mi
Registration #17	2018-01-22	65.317 mi
Registration #18	2018-01-22	65.317 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1539 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBAJ3070542