





report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date 2021-12-13

Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-11-06

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-11-06

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



RK66VCM report date: 2024-03-28

MOT history

MOT expiry date	2024-09-20
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #6		2023-09-01 11:57
MOT test	number	568215399017
Result		✓ Passed
Next expi	y date	2024-09-20
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2022-09-09 09:36
MOT test number	618877019511
Result	✓ Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4	2021-09-13 13:45
MOT test number	642010959628
Result	√ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

991187355075

Result

Minor

Nearside Front Windscreen wiper blade defective Split (3.4 (b) (i))

MAJOR

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor

Offside Front Windscreen wiper blade defective Split (3.4 (b) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2

MOT test number

Result

Advice Brake pad(s) wearing thin front and rear (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake disc worn, but not excessively front and rear (1.1.14 (a) (i))

MOT #1	2019-08-23 13:52
MOT test number	996590951056
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

RK66VCM

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 9/11



RK66VCM report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-21
Last registration	2023-09-01
Complete history	See info



Registration #1	2016-09-21	16 mi
Registration #2	2019-08-23	18.540 mi
Registration #3	2020-09-16	24.564 mi
Registration #4	2021-09-08	30.924 mi
Registration #5	2021-09-13	31.012 mi
Registration "5	2021 03 13	00
Registration #6	2021 03 13	11.771 66
	2021 03 13	11.777 es 11.777 es
Registration #6	2021 03 13	11.777 es 11.777 es 11.777 es
Registration #6 Registration #7	2021 03 13	11.777 ea 11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 10/11



RK66VCM report date: 2024-03-28

Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225 Air conditioning
S0295

\$0482 \$0501

\$0566 \$0567

S0569

View the complete HYUNDAI factory list for this vehicle <u>here</u>.

More info >

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	1977 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/

Number of axles 2

Engine number D4HBGU494349