



PEUGEOT



S33PSW


report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 COUPE SE
Colour	Silver
Year of manufacture	2007
Top speed	138 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	220 Nm at 4.150 rpm
Engine capacity	2.230 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	40.9 mpg
Consumption combined	30.7 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-20
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-09-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	16
Total items failed	13

MOT #18	2021-09-30 10:59
MOT test number	545468239866
Result	✓ Passed
Next expiry date	2022-09-29
Advice	Tpw warning lamp on

MOT #17	2021-09-29 11:58
MOT test number	322878506601
Result	✗ Failed
Fail	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
Fail	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
Advice	Nearside headlamp dim
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Tpw warning lamp on

MOT #16	2020-07-28 13:54
MOT test number	619655787945
Result	✓ Passed

**MOT #15** 2020-07-28 10:04**MOT test number** 563744976267**Result** ✗ Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #14 2019-06-05 08:39**MOT test number** 776631928009**Result** ✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2018-06-05 09:09**MOT test number** 950509638128**Result** ✓ Passed**MOT #12** 2017-06-08 10:29**MOT test number** 308375445432**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2017-06-08 10:29**MOT test number** 931660042289**Result** ✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2016-05-16 09:48**MOT test number** 177375310660**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-05-16 09:48**MOT test number** 377395754415**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #8** 2015-04-27 15:13**MOT test number** 145547215181**Result** ✓ Passed**MOT #7** 2015-04-23 14:10**MOT test number** 767153315189**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #6** 2014-05-12 10:51**MOT test number** 887262934117**Result** ✓ Passed**MOT #5** 2013-04-30 10:52**MOT test number** 769010623123**Result** ✓ Passed

**MOT #4** 2012-04-26 12:36**MOT test number** 425237112111**Result** ✓ Passed**MOT #3** 2012-04-20 11:47**MOT test number** 629071212176**Result** ✗ Failed**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Lower Ball joint has excessive play (2.2.B.1f)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2011-05-12 15:40**MOT test number** 968822531150**Result** ✓ Passed**MOT #1** 2010-03-16 12:14**MOT test number** 551515770075**Result** ✓ Passed**Advice** Nearside Inner Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Outer Rear brake disc slightly pitted (3.5.1h)**Advice** Offside Inner Front brake disc slightly pitted (3.5.1h)**Advice** Offside Outer Rear brake disc slightly pitted (3.5.1h)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-01
Last registration	2021-09-30
Complete history	See info



Registration #1	2007-03-01	18 mi
Registration #2	2010-03-16	20.800 mi
Registration #3	2011-05-12	25.528 mi
Registration #4	2012-04-20	30.780 mi
Registration #5	2012-04-26	30.784 mi
Registration #6	2013-04-30	40.134 mi
Registration #7	2014-05-12	48.122 mi
Registration #8	2015-04-23	53.647 mi
Registration #9	2015-04-27	53.672 mi
Registration #10	2016-05-16	58.876 mi
Registration #11	2016-05-16	58.876 mi
Registration #12	2016-05-16	58.876 mi
Registration #13	2016-05-16	58.876 mi
Registration #14	2016-05-16	58.876 mi
Registration #15	2016-05-16	58.876 mi
Registration #16	2016-05-16	58.876 mi
Registration #17	2016-05-16	58.876 mi
Registration #18	2016-05-16	58.876 mi
Registration #19	2016-05-16	58.876 mi
Registration #20	2016-05-16	58.876 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1868 mm
Height	1399 mm
Length	4815 mm
Wheel base	2725 mm
Kerb weight	1600 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LJ431433739