



General information

Make	VOLKSWAGEN
Model	PASSAT BLUEMOTION TDI
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg



**MOT history**

MOT #13	2023-03-27 17:39
MOT test number	675891705356
Result	✓ Passed
Next expiry date	2024-03-26
Advice	Under tray fitted to the car
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Front and rear disc pitted
Advice	Covers on sills inner and outer sills both sides
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #12	2022-03-21 12:56
MOT test number	987363488547
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2021-03-11 15:55
MOT test number	203360132545
Result	✓ Passed

MOT #10	2020-02-17 17:42
MOT test number	637842539283
Result	✓ Passed

MOT #9	2020-02-15 14:58
MOT test number	814409620879
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #8** 2019-03-14 08:53**MOT test number** 505157999222**Result** ✓ Passed**MOT #7** 2019-03-13 11:30**MOT test number** 414255839476**Result** ✗ Failed

- MAJOR** Offside Rear Position lamp not working (4.2.1 (a))
- MAJOR** Offside Headlamp aim too high (4.1.2 (a))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- MAJOR** Nearside Headlamp aim too high (4.1.2 (a))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #6 2018-03-10 14:41**MOT test number** 773475108912**Result** ✓ Passed**Advice** Engine management**MOT #5** 2017-03-11 09:56**MOT test number** 677395142464**Result** ✓ Passed**Advice** Nearside Front tyre wearing on outer wall**MOT #4** 2016-03-14 16:01**MOT test number** 812674000688**Result** ✓ Passed



MOT #3	2015-05-21 10:26
MOT test number	526341345122
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #2	2014-06-12 11:38
MOT test number	298083864143
Result	✓ Passed

MOT #1	2013-06-11 14:03
MOT test number	198742663192
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Nsf tyre worn on inner
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-06-26
Last registration	2023-03-27
Complete history	See info



Registration #1	2010-06-26	26 mi
Registration #2	2013-06-11	48.302 mi
Registration #3	2014-06-12	63.407 mi
Registration #4	2015-05-21	79.345 mi
Registration #5	2016-03-14	93.715 mi
Registration #6	2017-03-11	111.252 mi
Registration #7	2018-03-10	125.492 mi
Registration #8	2019-03-27	141.277 mi
Registration #9	2020-03-27	158.277 mi
Registration #10	2021-03-27	176.277 mi
Registration #11	2022-03-27	195.277 mi
Registration #12	2023-03-27	215.277 mi
Registration #13	2024-03-27	236.277 mi
Registration #14	2025-03-27	258.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1530 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAY 757583