





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

_		•		_	-
-	n	т	rv	,	

Date	2021-05-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-10-18
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #10	2023-10-19 11:27
MOT test number	115007506421
Result	✓ Passed
Next expiry date	2024-10-18

MOT #9		2023-10-17 11:18
MOT test	number	356322932313
Result		X Failed
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #8	2022-08-16 08:40
MOT test number	366134952481
Result	✓ Passed
Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #7	2021-09-10 12:08
MOT test number	450359704694
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6		2020-09-02 07:10
MOT test	number	369531099896
Result		✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping e	effect (5.3.2 (b))
Advice	Nearside Rear Service brake grabbing slightly (1.2.1 (c))	
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping	effect (5.3.2 (b))
Advice	Offside Rear Service brake grabbing slightly (1.2.1 (c))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))

MOT #5		2020-09-01 09:21
MOT test	number	668390399036
Result		★ Failed
Advice	Nearside Rear Service brake grabbing slightly (1.2.1 (c))	
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping	g effect (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Offside Rear Service brake grabbing slightly (1.2.1 (c))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping of	effect (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outside edge	wear (5.2.3 (e))

MOT #4	2019-08-14 12:37
MOT test number	507576491101
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2018-08-09 10:32

MOT test number 456279438950

MOT #2 2017-09-04 09:59

MOT test number 495981711762

Result

✓ Passed

MOT #1 2017-09-04 08:43

MOT test number 582905303955

Result X Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

SG64MPZ

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owners did this REI have? Check it in the premium report and see all owner registrations. Download the full report here .	NAULT

More info	>
Plate changes	
See in this check if this RENAULT had different number plates.	

ボ UK

UK

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-03
Last registration	2023-10-19
Complete history	See info



Registration #1	2014-09-03	7 mi
Registration #2	2017-09-04	18.962 mi
Registration #3	2017-09-04	18.962 mi
Registration #4	2018-08-09	29.318 mi
Registration #5	2019-08-14	45.630 mi
Registration #6	2020-09-01	53.220 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	ge 12/12

Number of axles2Engine numberD411701