




report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S
Colour	Blue
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-09-06
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	15
Total items failed	9

MOT #16	2023-11-02 11:31
MOT test number	145742098077
Result	✓ Passed
Next expiry date	2024-11-01

MOT #15	2023-11-02 11:31
MOT test number	601016910251
Result	✗ Failed
Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #14	2022-10-14 13:05
MOT test number	185108632765
Result	✓ Passed

MOT #13	2022-10-06 11:31
MOT test number	589908071979
Result	✗ Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	

**MOT #12** 2021-10-19 13:23**MOT test number** 532321226127**Result** ✓ Passed**MOT #11** 2021-10-08 14:08**MOT test number** 183444449205**Result** ✗ Failed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Outer Brake pipe excessively corroded (1.1.11 (c))**MOT #10** 2021-06-01 15:36**MOT test number** 257750867144**Result** ✓ Passed**Advice** Front Brake pipe corroded, covered in grease or other material both front pipes corroded (1.1.11 (c))**Advice** Rear Brake pipe corroded, covered in grease or other material both rear pipes corroded (1.1.11 (c))**MOT #9** 2021-06-01 13:25**MOT test number** 187224147727**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt drop link boot split (5.3.4 (b) (ii))**Advice** Rear rear axle corroded**Advice** Front Brake pipe corroded, covered in grease or other material both front pipes corroded (1.1.11 (c))**Advice** Front suspension components corroded**Advice** Front Tyre slightly damaged both front tyres cracking (5.2.3 (d) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material both rear pipes corroded (1.1.11 (c))

**MOT #8** 2020-06-18 14:31**MOT test number** 745967413895**Result** ✓ Passed**MOT #7** 2019-10-25 16:21**MOT test number** 576040497767**Result** ✓ Passed**Advice** Rear both tyres cracking slightly**MOT #6** 2018-11-01 14:26**MOT test number** 651090404878**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2018-10-31 13:10**MOT test number** 320945942299**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Brake performance not tested (1.2.1 (g))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2017-07-03 15:52**MOT test number** 850018023322**Result** ✓ Passed



MOT #3	2016-04-08 14:44
MOT test number	925480711388
Result	✗ Failed
Advice	Offside Rear tyre perishing
Advice	Nearside Rear tyre perishing
Fail	Offside Front coil spring broken (2.4.C.1a)

MOT #2	2015-07-15 11:39
MOT test number	635396195119
Result	✓ Passed

MOT #1	2014-07-01 10:34
MOT test number	285092484406
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-07-25
Last registration	2023-11-02
Complete history	See info



Registration #1	2011-07-25	15 mi
Registration #2	2014-07-01	25.243 mi
Registration #3	2015-07-15	30.743 mi
Registration #4	2016-04-08	32.221 mi
Registration #5	2017-07-03	44.728 mi
Registration #6	2018-10-31	60.982 mi
Registration #7	2018-11-01	60.983 mi
Registration #8	2019-10-25	62.600 mi
Registration #9	2020-06-18	62.616 mi
Registration #10	2020-06-18	62.616 mi
Registration #11	2020-06-18	62.616 mi
Registration #12	2020-06-18	62.616 mi
Registration #13	2020-06-18	62.616 mi
Registration #14	2020-06-18	62.616 mi
Registration #15	2020-06-18	62.616 mi
Registration #16	2020-06-18	62.616 mi
Registration #17	2020-06-18	62.616 mi
Registration #18	2020-06-18	62.616 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1331429