





General information

Make	CITROEN	
Model	DS3 E-HDI DSTYLE PLUS	
Colour	Silver	
Year of manufacture	2014	
Top speed	113 mph	
0 - 60 mph	12.5 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	90 BHP	
Max. torque	230 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	64.2 mpg	
Consumption extra urban	85.6 mpg	
Consumption combined	76.4 mpg	
CO2 emission	95 g/km	
CO2 label	А	







Internet history

Entry 1

Date Pictures 2021-01-29

10

Listing price

View report







source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-14
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #9	2023-05-10 14:47
MOT test number	578105674638
Result	✓ Passed
Next expiry date	2024-05-14

MOT #8	2022-05-12 14:19
MOT test number	160045777090
Result	✓ Passed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Advice Rear Exhaust mounting defective mounting broken (6.1.2 (a))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm and w (e))	vorn on inner edge (5.2.3
Advice Front Brakes imbalanced requirements only just met. It would appear the requires adjustment or repair. (1.2.1 (b) (i))	at the braking system
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #7	2022-05-12 13:52
MOT test number	774381510510
Result	🗙 Failed
Fail Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))
Advice Rear Exhaust mounting defective mounting broken (6.1.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm and worn on (e))	inner edge (5.2.3
FailOffside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front Brakes imbalanced requirements only just met. It would appear that the brequires adjustment or repair. (1.2.1 (b) (i))	raking system
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))
Advice Items removed from driver's view prior to test	
Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer pringress of dirt boot not secured (6.1.7 (g) (ii))	prevents the

MOT #6	2021-05-15 16:32
MOT test number	592503874230
Result	✓ Passed
Advice Underbody protective covers fitted obstructing some areas	





MOT #5	2021-05-15 15:40
MOT test number	188668597961
Result	🗙 Failed
Advice Underbody protective covers fitted obstructing some areas	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Front Registration plate insecure (0.1 (a))	
Fail Front Windscreen washer not working (3.5 (a))	
Fail Rear Registration plate insecure (0.1 (a))	

MOT #4		2019-05-08 10:18
MOT test	number	511328098647
Result		✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #3	2018-05-09 15:06
MOT test number	576287675520
Result	✓ Passed
MOT #2	2017-05-17 10:02

MOT test number	422839045454
Result	✓ Passed





MOT #1		2017-05-17 10:02
MOT test number		576621711367
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)	
Pass with rectification	Nearside Rear Headlamp aim too low (1.8)	



Tax & MOT check

Tax due: 1 May 2025	✓ Taxed	Expires: 14 May 2024	✓ МОТ
Tax status			Valid until 1 May
Days left			367
MOT expiry date			14 May 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		LAMP
Туре		
Damage 2		XAMPL
Date		
Category		SN61
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-04
Last registration	2023-05-10
Complete history	<u>See info</u>



Registration #1	2014-03-04	15 mi
Registration #2	2017-05-17	14.275 mi
Registration #3	2017-05-17	14.275 mi
Registration #4	2018-05-09	18.178 mi
Registration #5	2019-05-08	35.483 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.117 esi





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 3