



TOYOTA



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | TOYOTA |
| Model | C-HR DESIGN |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 118 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 185 Nm at 4.000 rpm |
| Engine capacity | 1.197 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 41.5 mpg |
| CO2 emission | 138 g/km |
| CO2 label | E |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-02 |
| Pictures | 14 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-17 |
| MOT pass rate | 43 % |
| MOT passed | 3 |
| Failed MOT tests | 4 |
| Total advice items | 37 |
| Total items failed | 10 |

| | |
|------------------|---|
| MOT #7 | 2024-04-18 12:44 |
| MOT test number | 965265646447 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-17 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2mm. centre 75% of tread (5.2.3 (e)) |
| Advice | Minor bush bond separation near side front lower suspension arm |
| Advice | Both rear tyres outer edges and walls perished |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 2mm. centre 75% of tread (5.2.3 (e)) |
| Advice | Front registration plate damaged |

| | |
|-----------------|--|
| MOT #6 | 2024-03-30 15:47 |
| MOT test number | 397574808362 |
| Result | ✗ Failed |
| Minor | Central Rear Windscreen wiper blade defective (3.4 (b) (i)) |
| Advice | Front Registration plate insecure but not likely to fall off (0.1 (a)) |
| Fail | Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |



MOT #5

2024-03-13 17:29

MOT test number

888709771124

| Result | | ✗ Failed |
|--------|--|----------|
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | |
| Advice | Offside Front Service brake binding but not excessively (1.2.1 (f)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Fail | Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) | |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Registration plate insecure but not likely to fall off (0.1 (a)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Fail | Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) | |



MOT #4

2024-03-06 16:37

MOT test number

617497508894

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Registration plate insecure but not likely to fall off (0.1 (a))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #3**

2023-11-21 15:06

MOT test number

320960770581

Result

✗ Failed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Registration plate insecure (0.1 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #2

2022-10-12 15:22

MOT test number

766502643027

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both Sides Front (1.1.14 (a) (ii))
- Advice** Nearside Front Nail in tyre
- Advice** Rear Tyre slightly damaged/cracking or perishing Both Sides Rear Outer wall (5.2.3 (d) (ii))

MOT #1

2021-07-21 10:32

MOT test number

825919186566

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
17 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 156 |
| MOT expiry date | 17 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2018-09-21 |
| Last registration | 2024-04-18 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-09-21 | 13 mi |
| Registration #2 | 2021-07-21 | 27.004 mi |
| Registration #3 | 2022-10-12 | 36.581 mi |
| Registration #4 | 2023-11-21 | 45.346 mi |
| Registration #5 | | |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |
| Registration #9 | | |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 95% |
| Children | 77% |
| Pedestrian | 76% |
| Safety systems | 78% |
| Overall rating | 84% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1795 mm |
| Height | 1565 mm |
| Length | 4360 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1375 kg |
| Max. allowed weight | 1845 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 43 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | 8NRU224977 |