



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Red
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 2

Date	2023-08-23
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-23
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-07
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	11
Total items failed	13

MOT #12	2023-10-02 14:54
MOT test number	852954896752
Result	✓ Passed
Next expiry date	2024-10-07

MOT #11	2022-10-03 14:15
MOT test number	165575450590
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10	2021-10-08 09:49
MOT test number	753247146944
Result	✓ Passed

**MOT #9**

2021-10-06 10:11

MOT test number

727974615457

Result

✗ Failed

- Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Macpherson strut mounting likely to fail (5.3.3 (b) (ii))
- Fail** Nearside Front Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))
- Advice** Nearside Front ABS wiring insecure
- Advice** Nearside Rear Nail in tyre
- Fail** Nearside Rear Side repeater incorrect colour (4.4.3 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Direction indicator not working (4.4.1 (a) (ii))
- Fail** Offside Rear Side repeater incorrect colour (4.4.3 (a))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #8

2021-01-15 16:27

MOT test number

457243544570

Result

✓ Passed

- Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #7** 2021-01-15 13:31**MOT test number** 373018404921**Result** ✗ Failed**Fail** Front Suspension arm pin or bush excessively worn both (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin on the limit (1.1.13 (a) (ii))**MOT #6** 2019-07-15 09:47**MOT test number** 385072822344**Result** ✓ Passed**MOT #5** 2018-07-10 15:41**MOT test number** 151010519272**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2017-07-15 10:02**MOT test number** 723338973764**Result** ✓ Passed**Advice** Nearside Front slight damage to tyre sidewall



MOT #3	2017-07-15 09:02
MOT test number	255136470601
Result	✗ Failed
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Nearside Front slight damage to tyre sidewall
Fail	Windscreen wiper does not clear the windscreen effectively both (8.2.2)

MOT #2	2016-07-08 08:29
MOT test number	951510355604
Result	✓ Passed

MOT #1	2015-07-17 13:29
MOT test number	560627412678
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
7 October 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	7 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	WG12HWD
Plate since	2019-09-28
Current registration	WG12HWD
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-03
Last registration	2023-10-02
Complete history	See info



Registration #1	2012-07-03	16 mi
Registration #2	2015-07-17	34.821 mi
Registration #3	2016-07-08	39.627 mi
Registration #4	2017-07-15	43.828 mi
Registration #5	2017-07-15	43.834 mi
Registration #6	2018-07-10	48.041 mi
Registration #7	2019-07-15	51.882 mi
Registration #8	2021-01-15	59.159 mi
Registration #9	2022-05-20	65.277 mi
Registration #10	2022-05-20	65.277 mi
Registration #11	2022-05-20	65.277 mi
Registration #12	2022-05-20	65.277 mi
Registration #13	2022-05-20	65.277 mi
Registration #14	2022-05-20	65.277 mi
Registration #15	2023-10-02	71.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033