



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 MILLESIM
Colour	Red
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-05-21
Pictures	33
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-05-14
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	40
Total items failed	11

MOT #15 2023-05-11 17:18**MOT test number** 779465809821**Result** Passed**Next expiry date** 2024-05-14**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2022-05-14 08:47**MOT test number** 137389186930**Result** Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Exhaust system corroded**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #13**

2022-05-07 10:56

MOT test number

921370084936

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust system corroded
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12

2021-05-15 08:00

MOT test number

597074236735

Result**✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-05-14 11:30

MOT test number

181361037329

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10

2020-07-24 13:02

MOT test number

988011346808

Result**✓ Passed**

- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Exhaust corroded / hangers / welds / joints
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive Various (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2019-07-23 13:21

MOT test number

666046225757

Result**✓ Passed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2019-07-22 14:12**MOT test number** 656051071830**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Brakes imbalanced across an axle 40% (1.2.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #7** 2017-11-28 16:21**MOT test number** 149285661909**Result** ✓ Passed**MOT #6** 2017-11-28 10:40**MOT test number** 208384665372**Result** ✗ Failed**Fail** Nearside rear brake binding (3.7.B.1)**MOT #5** 2016-10-11 12:49**MOT test number** 766298540799**Result** ✓ Passed

**MOT #4** 2016-10-11 12:49**MOT test number** 881848830983**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2015-06-15 10:04**MOT test number** 977616665188**Result** ✓ Passed**MOT #2** 2014-06-02 10:29**MOT test number** 298023554112**Result** ✓ Passed**MOT #1** 2013-06-15 09:40**MOT test number** 736826163149**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-




Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-29
Last registration	2023-05-11
Complete history	See info



Registration #1	2010-06-29	24 mi
Registration #2	2013-06-15	45.302 mi
Registration #3	2014-06-02	58.312 mi
Registration #4	2015-06-15	67.354 mi
Registration #5	2016-10-11	72.616 mi
Registration #6	2016-10-11	72.616 mi
Registration #7	2017-11-28	77.766 mi
Registration #8	2017-11-28	77.767 mi
Registration #9	2019-07-22	79.854 mi
Registration #10	2019-07-22	79.854 mi
Registration #11	2019-07-22	79.854 mi
Registration #12	2019-07-22	79.854 mi
Registration #13	2019-07-22	79.854 mi
Registration #14	2019-07-22	79.854 mi
Registration #15	2019-07-22	79.854 mi
Registration #16	2019-07-22	79.854 mi
Registration #17	2019-07-22	79.854 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	6589212
---------------	---------