



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Green
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	212 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-27
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	37
Total items failed	5

MOT #18	2023-11-28 14:14
MOT test number	915552110913
Result	✓ Passed
Next expiry date	2024-11-27

MOT #17	2023-11-27 16:58
MOT test number	276096772262
Result	✗ Failed
MAJOR Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #16	2023-01-14 11:59
MOT test number	572458829431
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Surface corrosion to underside of vehicle	

**MOT #15** 2023-01-13 17:01**MOT test number** 818353709273**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Surface corrosion to underside of vehicle
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14** 2021-12-13 12:41**MOT test number** 449302302164**Result** ✓ Passed

- Advice** Front and Rear sub-frames undercoated

**MOT #13** 2021-01-13 10:00**MOT test number** 123374806846**Result** ✓ Passed**MOT #12** 2021-01-05 08:38**MOT test number** 642552091738**Result** ✗ Failed

- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Power steering pipe/hose leaking (2.1.5 (a))

**MOT #11** 2019-12-03 14:00**MOT test number** 592078062764**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #10** 2018-11-19 16:41**MOT test number** 489620097502**Result** ✓ Passed**MOT #9** 2018-11-19 14:27**MOT test number** 447663567541**Result** ✗ Failed**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #8** 2017-08-30 14:01**MOT test number** 643375282325**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-08-29 10:35**MOT test number** 247536260452**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2016-08-10 09:09**MOT test number** 110940261044**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt small hole (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #5**

2016-08-09 08:26

**MOT test number**

982923700402

**Result****✗ Failed**

- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Under bonnet release lever very stiff
- Advice** Offside Rear Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt small hole (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4**

2015-08-28 08:21

**MOT test number**

923579834330

**Result****✓ Passed**

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #3**

2014-07-29 16:53

**MOT test number**

548230314271

**Result****✓ Passed****MOT #2**

2014-07-23 14:27

**MOT test number**

766474004259

**Result****✗ Failed**

- Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Offside Rear Radius arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #1	2013-06-26 11:01
MOT test number	466577973141
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
27 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	27 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-03
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2010-09-03	7 mi
Registration #2	2013-06-26	46.558 mi
Registration #3	2014-07-23	52.467 mi
Registration #4	2014-07-29	52.467 mi
Registration #5	2015-08-28	55.477 mi
Registration #6	2016-08-09	60.387 mi
Registration #7	2016-08-10	60.387 mi
Registration #8	2017-08-29	64.463 mi
Registration #9	2017-08-30	64.475 mi
Registration #10	2018-11-19	69.128 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1887 kg
Max. allowed weight	2390 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	822796