



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Silver
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2021-06-21
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	16
Total items failed	4

MOT #10	2020-06-22 14:12
MOT test number	553676693516
Result	✓ Passed
Next expiry date	2021-06-21
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Central Exhaust has a minor leak of exhaust gases Exhaust system corroded (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2020-06-22 10:50**MOT test number** 856284301416**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases Exhaust system corroded (6.1.2 (a))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #8** 2019-01-22 12:02**MOT test number** 832884237791**Result** ✓ Passed**MOT #7** 2018-01-09 12:14**MOT test number** 410853904860**Result** ✓ Passed

- Advice** Front Inner brake discs corroded
- Advice** Under trays fitted

**MOT #6** 2018-01-08 14:42**MOT test number** 730425747465**Result** ✗ Failed**Advice** Front Inner brake discs corroded**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Under trays fitted**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2016-06-18 07:57**MOT test number** 960859889444**Result** ✓ Passed**MOT #4** 2015-07-04 09:07**MOT test number** 927985885126**Result** ✓ Passed**MOT #3** 2014-07-04 13:59**MOT test number** 645055784190**Result** ✓ Passed**Notice** Rear exhaust system corroded**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-06-28 16:58**MOT test number** 519879673164**Result** ✓ Passed**MOT #1** 2012-06-30 09:07**MOT test number** 867432982106**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX


More info >





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-07-17
Last registration	2020-06-22
Complete history	<a href="#">See info</a>



Registration #1	2009-07-17	24 mi
Registration #2	2012-06-30	39.186 mi
Registration #3	2013-06-28	50.200 mi
Registration #4	2014-07-04	63.474 mi
Registration #5	2015-07-04	74.026 mi
Registration #6	2016-06-18	87.818 mi
Registration #7	2017-06-22	101.610 mi
Registration #8	2018-06-22	115.402 mi
Registration #9	2019-06-22	129.194 mi
Registration #10	2020-06-22	142.986 mi
Registration #11	2021-06-22	156.778 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

BZG258667