



FL04MLE

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T200 SWB P/V
Colour	White
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-21
Pictures	7
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2021-03-02
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	40
Total items failed	27

MOT #192020-03-03 14:36

MOT test number253311439612

Result✓ Passed

Next expiry date2021-03-02

- Advice

Nearside Rear park effort low
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside sill corrosion
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Nearside sill corrosion
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2018-12-19 14:45

MOT test number

891725557050

Result

✓ Passed

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Both sills slight corrosion

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17

2017-10-31 16:13

MOT test number

480697402989

Result

✓ Passed

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



MOT #16

2016-11-17 15:52

MOT test number

318510368263

Result		✗ Failed
Advice	Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Advice	Brake pipe slightly corroded front to rear (3.6.B.2c)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Fail	Nearside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)	
Fail	Brake pedal anti-slip provision worn smooth (3.3.A.1b)	
Fail	Nearside Front Anti-roll bar linkage fractured (2.4.G.1)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Fail	Nearside Rear Stop lamp not working (1.2.1b)	
Fail	Offside Rear Suspension spring mounting prescribed area is excessively corroded outer sill (2.4.A.3)	
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)	

**MOT #15**

2016-11-17 09:48

MOT test number

766828757435

Result**✗ Failed****Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)**Fail** Nearside Front Anti-roll bar linkage fractured (2.4.G.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #14**

2015-09-21 15:50

MOT test number

851509239507

Result**✓ Passed****MOT #13**

2015-09-14 11:36

MOT test number

381549823470

Result**✗ Failed****Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings sill (6.1.B.2)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)



MOT #12	2014-09-24 08:54
MOT test number	345817964229
Result	✓ Passed
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #11	2014-09-22 12:56
MOT test number	156425064245
Result	✗ Failed
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Brake pipe excessively corroded (3.6.B.2c)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Fail	Offside Rear Brake pipe excessively corroded (3.6.B.2c)
Advice	Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #10	2013-07-06 13:13
MOT test number	588877283125
Result	✓ Passed

**MOT #9** 2012-03-07 10:58**MOT test number** 718037362010**Result** ✓ Passed**Notice** Nearside seatbelt upper anchorage height adjuster faulty but anchor secure**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2012-03-06 14:34**MOT test number** 908926862099**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Nearside seatbelt upper anchorage height adjuster faulty but anchor secure**Fail** Offside Headlamp aim too low (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Oil leak**MOT #7** 2011-03-04 13:45**MOT test number** 868053461010**Result** ✓ Passed**MOT #6** 2010-03-16 09:22**MOT test number** 211815970093**Result** ✓ Passed

**MOT #5** 2009-03-20 10:59**MOT test number** 774449179042**Result** ✓ Passed

- Notice** O/s front tyre worn near to limit
- Notice** Windscreen cracked
- Notice** Front brake discs worn
- Notice** N/s rear tyre near to limit & has nail in

MOT #4 2008-03-26 09:36**MOT test number** 173056488044**Result** ✓ Passed

- Notice** Nail in rear tyre

MOT #3 2008-03-26 09:36**MOT test number** 713256888008**Result** ✗ Failed

- Notice** Nail in rear tyre
- Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)

MOT #2 2007-03-27 08:58**MOT test number** 381496687042**Result** ✓ Passed**MOT #1** 2007-03-27 08:58**MOT test number** 682636087051**Result** ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Centre Stop lamp not working (1.2.1b)



Tax & MOT check

✕
Untaxed

Tax expired:
1 November 2020

✕
MOT

Expired:
2 March 2021

Tax status

Expired at 1 November 2020

Days left

1274 days too late

MOT expiry date

2 March 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2004-03-30
Last registration	2020-03-03
Complete history	See info



Registration #1	2004-03-30	16 mi
Registration #2	2007-03-27	74.941 mi
Registration #3	2008-03-26	103.990 mi
Registration #4	2009-03-20	130.732 mi
Registration #5	2010-03-16	153.998 mi
Registration #6	2011-03-04	168.088 mi
Registration #7	2012-03-06	176.280 mi
Registration #8	2012-03-07	176.290 mi
Registration #9	2013-07-06	186.864 mi
Registration #10	2013-07-06	186.864 mi
Registration #11	2013-07-06	186.864 mi
Registration #12	2013-07-06	186.864 mi
Registration #13	2013-07-06	186.864 mi
Registration #14	2013-07-06	186.864 mi
Registration #15	2013-07-06	186.864 mi
Registration #16	2013-07-06	186.864 mi
Registration #17	2013-07-06	186.864 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1795 mm
Kerb weight	1400 kg
Max. allowed weight	2025 kg

Additional information

Number of seats	2
Number of axles	2
Engine number	4D07814