



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-17
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT #29	2022-03-16 17:11
MOT test number	456463953333
Result	✓ Passed
Next expiry date	2023-03-22

MOT #28	2022-03-16 14:52
MOT test number	526005242114
Result	✗ Failed

**Fail** Front Registration plate insecure (0.1 (a))

**Fail** Front Bumper insecure (6.1.4 (a) (i))

MOT #27	2021-03-08 10:50
MOT test number	136635419251
Result	✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened All discs (1.1.14 (a) (ii))

MOT #26	2021-03-08 10:50
MOT test number	643350354515
Result	✗ Failed

**Pass with rectification** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened All discs (1.1.14 (a) (ii))

**MOT #25**

2020-03-16 10:42

**MOT test number**

991045876791

**Result**

✓ Passed

- Minor** Headlamp lens slightly defective both lenses faded (4.1.1 (b) (i))
- Advice** Rear wiper blade poor
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Damage to n/s/f bumper.
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #24**

2020-03-16 10:42

**MOT test number**

101971334603

**Result**

✗ Failed

- Minor** Headlamp lens slightly defective both lenses faded (4.1.1 (b) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Damage to n/s/f bumper.
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear wiper blade poor

**MOT #23**

2019-03-11 10:07

**MOT test number**

206704639997

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mounting (5.3.6 (a) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear wiper damaged
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mount (5.3.6 (a) (i))
- Advice** Nearside Rear Nail in tyre

**MOT #22**

2019-03-11 10:07

**MOT test number**

736892456581

**Result**

✗ Failed

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mounting (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear wiper damaged
- Pass with rectification** Windscreen wiper does not clear the windscreen effectively both blades (3.4 (b) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mount (5.3.6 (a) (i))

**MOT #21**

2018-03-19 16:13

**MOT test number**

139842460940

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases Centre box (7.1.2)

**MOT #20** 2018-03-19 10:39**MOT test number** 616972294404**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Exhaust has a minor leak of exhaust gases Centre box (7.1.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #19** 2017-03-21 15:53**MOT test number** 721038251324**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #18** 2017-03-20 17:31**MOT test number** 124251145500**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Headlamp deteriorated but light output not reduced both lenses faded (1.7.5a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #17** 2016-03-23 13:57**MOT test number** 321704026201**Result** ✓ Passed

**MOT #16** 2016-03-23 13:57**MOT test number** 276647340517**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside front brake binding (3.7.B.1)**MOT #15** 2015-03-12 10:11**MOT test number** 265551675048**Result** ✓ Passed**MOT #14** 2015-03-12 10:11**MOT test number** 127881675012**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #13** 2014-03-14 14:52**MOT test number** 805043474012**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #12** 2014-03-13 15:05**MOT test number** 725212874042**Result** ✗ Failed**Fail** Front brake application uneven (3.7.B.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2013-03-15 17:04**MOT test number** 839344373093**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2013-03-14 15:00**MOT test number** 148153473046**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #9** 2012-03-08 12:14**MOT test number** 365758362049**Result** ✓ Passed



**MOT #8** 2012-03-08 09:28**MOT test number** 135988362450**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2011-03-09 10:04**MOT test number** 208948661019**Result** ✓ Passed**MOT #6** 2010-03-12 11:52**MOT test number** 854931970086**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-03-13 14:57**MOT test number** 684302479027**Result** ✓ Passed**MOT #4** 2009-03-13 11:35**MOT test number** 533592279050**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #3	2008-03-10 16:25
MOT test number	462240278052
Result	✓ Passed
MOT #2	2007-07-04 12:32
MOT test number	421475887158
Result	✓ Passed
MOT #1	2006-07-14 12:56
MOT test number	783245196117
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	30
First mileage registration	2003-07-23
Last registration	2022-03-16
Complete history	<a href="#">See info</a>



Registration #1	2003-07-23	29 mi
Registration #2	2006-07-14	25.254 mi
Registration #3	2007-07-04	32.684 mi
Registration #4	2008-03-10	37.607 mi
Registration #5	2009-03-13	44.730 mi
Registration #6	2009-03-13	44.730 mi
Registration #7	2010-03-12	49.434 mi
Registration #8	2011-03-09	57.065 mi
Registration #9	2012-03-08	66.947 mi
Registration #10	2012-03-08	66.947 mi
Registration #11	2013-03-14	77.962 mi
Registration #12	2013-03-15	77.962 mi
Registration #13	2014-03-13	86.111 mi
Registration #14	2014-03-14	86.115 mi
Registration #15	2015-03-12	89.477 mi
Registration #16	2016-03-12	95.377 mi
Registration #17	2016-03-12	95.377 mi
Registration #18	2016-03-12	95.377 mi
Registration #19	2016-03-12	95.377 mi
Registration #20	2016-03-12	95.377 mi
Registration #21	2016-03-12	95.377 mi
Registration #22	2016-03-12	95.377 mi
Registration #23	2016-03-12	95.377 mi
Registration #24	2016-03-12	95.377 mi
Registration #25	2016-03-12	95.377 mi
Registration #26	2016-03-12	95.377 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442

More info >





Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1215 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	3ZZU451723