



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2005
Top speed	143 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	218 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-07-10
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-09
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	9
Total items failed	3

MOT #19	2023-12-08 12:11
MOT test number	345368436057
Result	✓ Passed
Next expiry date	2024-12-09

MOT #18	2023-12-06 10:21
MOT test number	718541222703
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17	2022-12-06 10:06
MOT test number	740057165845
Result	✓ Passed

MOT #16	2021-12-10 12:14
MOT test number	634203977528
Result	✓ Passed

MOT #15	2020-09-08 10:35
MOT test number	479108855155
Result	✓ Passed

**MOT #14** 2019-09-10 08:14**MOT test number** 302400600599**Result** ✓ Passed**MOT #13** 2018-08-28 12:45**MOT test number** 831728056499**Result** ✓ Passed**MOT #12** 2017-09-14 14:01**MOT test number** 482915652011**Result** ✓ Passed**MOT #11** 2017-09-14 08:51**MOT test number** 327956692980**Result** ✗ Failed**Advice** Brake pipe slightly corroded Both front to rear brake pipes near rear of floor (3.6.B.2c)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint rear (2.4.G.2)**MOT #10** 2016-08-16 10:16**MOT test number** 135134472941**Result** ✓ Passed**MOT #9** 2015-09-02 11:06**MOT test number** 110295029539**Result** ✓ Passed

**MOT #8** 2014-08-29 14:47**MOT test number** 985001344217**Result** ✓ Passed

- Notice** Wipers smearing but not affecting view to road
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2013-09-04 14:33**MOT test number** 718227143229**Result** ✓ Passed**MOT #6** 2012-09-06 15:00**MOT test number** 349680552259**Result** ✓ Passed**MOT #5** 2010-09-21 12:00**MOT test number** 914314860222**Result** ✓ Passed**MOT #4** 2010-09-20 15:06**MOT test number** 162113560207**Result** ✗ Failed

- Fail** Nearside Front coil spring incomplete (2.4.C.1a)



MOT #3	2009-10-19 11:35
MOT test number	280182399257
Result	✓ Passed

MOT #2	2008-10-13 15:55
MOT test number	324067288222
Result	✓ Passed

MOT #1	2008-03-17 12:08
MOT test number	432727278017
Result	✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
9 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	9 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>OU05WYM</b>
Plate since	2019-05-29
Current registration	<b>OU05WYM</b>
Plate since	2019-05-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-19
Last registration	2023-12-08
Complete history	<a href="#">See info</a>



Registration #1	2005-03-19	20 mi
Registration #2	2008-03-17	15.135 mi
Registration #3	2008-10-13	18.167 mi
Registration #4	2009-10-19	20.814 mi
Registration #5	2010-09-20	22.345 mi
Registration #6	2010-09-21	22.345 mi
Registration #7	2012-09-06	25.049 mi
Registration #8	2013-09-04	28.590 mi
Registration #9	2014-08-29	30.854 mi
Registration #10	2015-09-02	33.616 mi
Registration #11	2016-08-16	34.993 mi
Registration #12	2019-05-20	35.377 mi
Registration #13	2019-05-20	35.377 mi
Registration #14	2019-05-20	35.377 mi
Registration #15	2019-05-20	35.377 mi
Registration #16	2019-05-20	35.377 mi
Registration #17	2019-05-20	35.377 mi
Registration #18	2019-05-20	35.377 mi
Registration #19	2019-05-20	35.377 mi
Registration #20	2019-05-20	35.377 mi
Registration #21	2019-05-20	35.377 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430545299