





report date: 2024-03-28

#### General information

Make	NISSAN
Model	NOTE ACENTA
Colour	Black
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

		1
ᆮ	HLIV	-

Lifety 1	
Date	2021-10-16
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2024-08-16
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	15
Total items failed	6

MOT #9	2023-08-17 13:48
MOT test number	985793862771
Result	✓ Passed
Next expiry date	2024-08-16
Advice Nearside Front Suspension arm pin or bush worn but not resulting in SPLIT (5.3.4 (a) (i))	excessive movement BUSH

MOT #8	2023-08-17 08:59
MOT test number	708688097313
Result	<b>×</b> Failed
Fail Windscreen washer provides insufficient washer liquid BOTH (3.5 (a))	
Advice Offside Front Tyre worn close to legal limit/worn on edge AND SIDEWALL	SCRUBBED (5.2.3 (e))
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (	ii))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excellent (5.3.4 (a) (i))	essive movement BUSH
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice N/S WIPER NOT TESTED	

MOT #7	2022-08-01 10:41
MOT test number	798251041807
Result	✓ Passed
Advice BOTH FRONT TYRES WORN, SIDEWALLS SCRUBING.N/S/F WISH BONE SPLITTING.	

CarCheck.co.uk page 3/12



(c))

**VE15PWN** 

report date: 2024-03-28

**MOT #6** 2021-08-04 13:12 **MOT** test number 433262840653 ✓ Passed Result **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Brake pipe corroded, covered in grease or other material covered in grease (1.1.11

MOT #5 2020-08-05 12:58
MOT test number 695269521962

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

MOT #4 2019-05-09 08:21

**MOT test number** 801743818060

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush seperating (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush seperating (5.3.4 (a) (i))

MOT #3 2019-05-09 08:21

MOT test number 498377023403

**Result** X Failed

CarCheck.co.uk page 4/12

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush seperating (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush seperating (5.3.4 (a) (i))

Pass with rectification

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



report date: 2024-03-28



CarCheck.co.uk page 5/12



VE15PWN
report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	16 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
	Moro info

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-28
Last registration	2023-08-17
Complete history	See info



Registration #1	2015-05-28	11 mi
Registration #2	2018-05-17	9.758 mi
Registration #3	2018-05-17	9.758 mi
Registration #4	2019-05-09	13.242 mi
Registration #5	2019-05-09	13.242 mi
Registration #6	2020-08-05	16.635 mi
Registration #7		11.777 es
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1040 kg
Max. allowed weight	1510 kg

# Additional information

Fuel tank capacity	41 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

**Engine number** 094515R