



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | MINI |
| Model | PACEMAN ONE D |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 106 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 90 BHP |
| Max. torque | 215 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 115 g/km |
| CO2 label | C |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-23 |
| Pictures | 6 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-08 |
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 13 |
| Total items failed | 1 |

| | |
|------------------|------------------|
| MOT #8 | 2023-10-09 14:42 |
| MOT test number | 808948001620 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-08 |

| | |
|-----------------|--|
| MOT #7 | 2022-08-16 13:37 |
| MOT test number | 603663194880 |
| Result | ✓ Passed |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |

| | |
|-----------------|------------------|
| MOT #6 | 2021-08-17 15:49 |
| MOT test number | 415994149824 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #5 | 2020-08-17 08:54 |
| MOT test number | 277804184823 |
| Result | ✓ Passed |
| Advice | Nearside Non obligatory mirror damaged |
| Advice | Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) |

**MOT #4** 2019-04-03 15:04**MOT test number** 417330753054**Result** ✓ Passed**Advice** Offside Front Seat belt slightly damaged seatbelt frayed . (7.1.2 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner & outer edges not to cord at time of test. (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges badly worn but not to cord at time of test. (5.2.3 (e))**MOT #3** 2019-04-03 14:41**MOT test number** 566072427476**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner & outer edges not to cord at time of test. (5.2.3 (e))**Advice** Offside Front Seat belt slightly damaged seatbelt frayed . (7.1.2 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges badly worn but not to cord at time of test. (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2018-04-04 13:13**MOT test number** 315332684911**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2017-03-17 11:41**MOT test number** 408914921136**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 154 |
| MOT expiry date | 8 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-03-29 |
| Current registration | |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2014-03-27 |
| Last registration | 2023-10-09 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-03-27 | 11 mi |
| Registration #2 | 2017-03-17 | 13.297 mi |
| Registration #3 | 2018-04-04 | 18.496 mi |
| Registration #4 | 2019-04-03 | 25.095 mi |
| Registration #5 | 2019-04-03 | 25.095 mi |
| Registration #6 | 2019-04-03 | 25.095 mi |
| Registration #7 | 2019-04-03 | 25.095 mi |
| Registration #8 | 2019-04-03 | 25.095 mi |
| Registration #9 | 2019-04-03 | 25.095 mi |
| Registration #10 | 2019-04-03 | 25.095 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1789 mm |
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1310 kg |
| Max. allowed weight | 1820 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 47 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Engine number

70518699