



LY59HBO


report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Brown
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-24
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-16
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	39
Total items failed	14

MOT #19	2024-02-26 12:54
MOT test number	894948510853
Result	✓ Passed
Next expiry date	2025-03-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18	2024-02-26 12:54
MOT test number	175897630082
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #17** 2023-02-27 15:16**MOT test number** 125178642509**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #16** 2023-02-27 10:56**MOT test number** 101901666251**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2022-03-17 16:21**MOT test number** 495717146862**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14** 2022-03-17 12:47**MOT test number** 282975479027**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

**MOT #13**

2021-02-04 15:24

MOT test number

165175190991

Result

✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Steering column top bearing slightly worn (2.2.2 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing and n/s/r (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #12

2021-02-03 14:36

MOT test number

329281873821

Result

✗ Failed

- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing and both rear (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Lower Steering column universal joint insecure (2.1.3 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2020-02-27 15:45

MOT test number

977816813798

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively o/s/f ,n/s/r and o/s/r (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge at 1.6mm (5.2.3 (e))
- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre slightly damaged slightly out of shape (5.2.3 (d) (ii))

MOT #10

2020-02-27 12:49

MOT test number

433726659933

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge at 1.6mm (5.2.3 (e))
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid and o/s/f (3.5 (a))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick and o/s/f (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged slightly out of shape (5.2.3 (d) (ii))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Brake disc worn, but not excessively o/s/f ,n/s/r and o/s/r (1.1.14 (a) (i))

MOT #9

2019-03-01 10:31

MOT test number

281801099970

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing low and slight wear to inner edge (5.2.3 (e))

**MOT #8** 2018-02-09 17:12**MOT test number** 405067805980**Result** ✓ Passed**MOT #7** 2017-02-18 10:01**MOT test number** 609041786308**Result** ✓ Passed**MOT #6** 2016-02-13 10:47**MOT test number** 241995529022**Result** ✓ Passed**Advice** Nearside outer door sill damage**MOT #5** 2016-02-13 10:47**MOT test number** 466693307190**Result** ✗ Failed**Advice** Nearside outer door sill damage**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2015-02-03 14:36**MOT test number** 996494335026**Result** ✓ Passed**Notice** Slight damage to n/s outer door sill**MOT #3** 2015-02-03 09:39**MOT test number** 597474035051**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



MOT #2	2014-02-11 14:53
MOT test number	438902444075
Result	✓ Passed
<div>NoticeN/s outer door sill damage</div>	

MOT #1	2013-02-02 15:13
MOT test number	196283733497
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-02-13
Last registration	2024-02-26
Complete history	See info



Registration #1	2010-02-13	11 mi
Registration #2	2013-02-02	9.558 mi
Registration #3	2014-02-11	11.334 mi
Registration #4	2015-02-03	13.426 mi
Registration #5	2015-02-03	13.426 mi
Registration #6	2016-02-13	15.184 mi
Registration #7	2016-02-13	15.184 mi
Registration #8	2017-02-18	16.531 mi
Registration #9	2018-02-09	19.096 mi
Registration #10	2019-03-01	22.215 mi
Registration #11	2020-02-27	32.677 mi
Registration #12	2020-02-27	32.677 mi
Registration #13	2020-02-27	32.677 mi
Registration #14	2020-02-27	32.677 mi
Registration #15	2020-02-27	32.677 mi
Registration #16	2020-02-27	32.677 mi
Registration #17	2020-02-27	32.677 mi
Registration #18	2020-02-27	32.677 mi
Registration #19	2020-02-27	32.677 mi
Registration #20	2020-02-27	32.677 mi
Registration #21	2020-02-27	32.677 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0086665