



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA SXI 16V TWINPORT
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	144 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-08
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-13
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	29
Total items failed	2

MOT #19 2024-04-12 08:17**MOT test number** 576006423274**Result** ✓ Passed**Next expiry date** 2025-04-13**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #18** 2024-04-12 08:17**MOT test number** 680192294467**Result** ✗ Failed**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #17**

2023-04-12 11:20

MOT test number

943404926135

Result

✓ Passed

- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))
- Advice** Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16

2022-04-01 11:27

MOT test number

638667689393

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Outer Steering linkage ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Outer Steering linkage ball joint has slight play (2.1.3 (b) (i))

MOT #15

2021-04-14 13:59

MOT test number

481454238610

Result

✓ Passed

MOT #14

2021-04-14 13:59

MOT test number

218808714274

Result

✗ Failed

- Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #13** 2020-05-15 09:40**MOT test number** 386344194932**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2019-05-03 09:00**MOT test number** 386765750519**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2018-05-14 10:46**MOT test number** 672717403999**Result** ✓ Passed**Advice** Rear tyres perishing**MOT #10** 2017-05-15 13:18**MOT test number** 599961324231**Result** ✓ Passed**Advice** Rear tyres perishing / cracking in tread



MOT #9	2016-05-19 09:27
MOT test number	672825199559
Result	✓ Passed
MOT #8	2015-05-20 11:42
MOT test number	746700345101
Result	✓ Passed
MOT #7	2014-05-16 13:21
MOT test number	419276534148
Result	✓ Passed
MOT #6	2013-05-09 14:54
MOT test number	825139923143
Result	✓ Passed
MOT #5	2012-05-04 11:44
MOT test number	616795522199
Result	✓ Passed
MOT #4	2011-05-09 14:32
MOT test number	248099121428
Result	✓ Passed
MOT #3	2010-05-18 15:32
MOT test number	213828530198
Result	✓ Passed
MOT #2	2009-03-11 12:12
MOT test number	813770479000
Result	✓ Passed



MOT #1	2008-02-26 11:46
MOT test number	644927658067
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
13 April 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	13 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	OY05OMJ
Plate since	2019-06-29
Current registration	OY05OMJ
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-31
Last registration	2024-04-12
Complete history	See info



Registration #1	2005-03-31	20 mi
Registration #2	2008-02-26	23.609 mi
Registration #3	2009-03-11	30.196 mi
Registration #4	2010-05-18	37.543 mi
Registration #5	2011-05-09	43.017 mi
Registration #6	2012-05-04	48.463 mi
Registration #7	2013-05-09	53.289 mi
Registration #8	2014-05-16	56.972 mi
Registration #9	2015-05-20	62.619 mi
Registration #10	2016-05-19	65.591 mi
Registration #11	2017-05-15	68.670 mi
Registration #12	2018-05-20	71.757 mi
Registration #13	2019-05-20	74.844 mi
Registration #14	2020-05-20	77.931 mi
Registration #15	2021-05-20	81.018 mi
Registration #16	2022-05-20	84.105 mi
Registration #17	2023-05-20	87.192 mi
Registration #18	2024-05-20	90.279 mi
Registration #19	2025-05-20	93.366 mi
Registration #20	2026-05-20	96.453 mi
Registration #21	2027-05-20	99.540 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3839 mm
Wheel base	2491 mm
Kerb weight	979 kg
Max. allowed weight	1430 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Engine number	19EJ8321