





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 CRDI ACTIVE BLUE DRIVE
Colour	Grey
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history


Entry 2

Date 2021-09-01

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-08-11	
Pictures	20	
Listing price	<u>View report</u>	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-04-28
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #8		2023-04-28 14:56
MOT test	number	172484161239
Result		✓ Passed
Next expi	ry date	2024-04-28
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.75 mm (5.2.3 (e)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		

MOT #7	2023-04-28 10:44
MOT test number	212475336605
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge 2.	.0 mm (5.2.3 (e))
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Offside Front Tyre has ply or cords exposed and worn inner edge (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.75 mm (5.2.3 (e)))
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

CarCheck.co.uk page 3/11



MOT #6 2022-04-29 09:05

MOT test number 651568588327

Advice Offside Rear Nail in tyre

Advice Offside Front Tyre worn close to legal limit/worn on edge badly worn inner edge just pass at time

of test! (5.2.3 (e))

MOT #5 2021-04-23 10:14

MOT test number 773836244244

Result ✓ Passed

MOT #4 2020-04-09 10:56

MOT test number 842963945600

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-04-09 08:36

MOT test number 807009915654

Result \(\sqrt{Passed} \)

MOT #2 2018-04-11 08:06

MOT test number 793661763389

Result ✓ Passed

Advice Front TYRES WORN ON INNER EDGES

MOT #1 2017-04-04 08:44

MOT test number 525579967744

Result

Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	28 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CO.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-04-28
Last registration	2023-04-28
Complete history	See info



Registration #1	2014-04-28	16 mi
Registration #2	2017-04-04	25.305 mi
Registration #3	2018-04-11	32.095 mi
Registration #4	2019-04-09	40.642 mi
Registration #5	2020-04-09	48.027 mi
Registration #6	2021-04-23	50.376 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1380 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles 2

Engine number D4FBDZ557150