



report date: 2024-03-29

General information

Make	FIAT
Model	MULTIPLA JTD ELEGANZA EU4
Colour	Silver
Year of manufacture	2007
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	210 Nm at 3.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	43.5 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-05-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	53
Total items failed	7

MOT #19	2023-07-14 09:11
MOT test number	618132563878
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2023-07-13 08:06
MOT test number	830987635371
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17	2022-06-06 15:18
MOT test number	831085165889
Result	✓ Passed

**MOT #16**

2021-04-20 09:42

MOT test number

321774509178

Result

✓ Passed

- Advice** Front sub-frame rusty
- Advice** Rear axel rusty
- Advice** Both rear coil springs corroded
- Advice** Under-body panels fitted

MOT #15

2021-04-19 13:54

MOT test number

307235388126

Result

✗ Failed

- Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp With hazards on (4.2.3 (c))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 195/60/15 (5.2.3 (d) (i))
- Advice** Rear axel rusty
- Advice** Both rear coil springs corroded
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp With hazards on (4.2.3 (c))
- Advice** Front sub-frame rusty
- Advice** Under-body panels fitted

MOT #14

2020-04-15 14:08

MOT test number

771640319950

Result

✓ Passed

- Advice** Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2019-01-24 11:11

MOT test number

426143136668

Result

✓ Passed

- Advice** Power steering pipes slight leak
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Under-body panels fitted
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12

2018-01-29 14:37

MOT test number

891354521026

Result

✓ Passed

- Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Offside Rear Nail in tyre

MOT #11

2017-01-24 10:31

MOT test number

649349251575

Result

✓ Passed

- Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint rack (2.3.3b)
- Advice** Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)
- Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brakes slight uneven braking
- Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened face (3.5.1i)
- Advice** Undertrays fitted



MOT #102016-02-23 09:53

MOT test number904246358175

Result

✓ Passed

- Advice

Undertrays and engine covers fitted
- Advice

Nearside rear brake slight bind
- Advice

Obstruction removed
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside rear tyre slight damage to sidewall

MOT #92015-03-03 12:42

MOT test number987682865072

Result

✓ Passed

- Notice

Front tyres wearing on inner edges [wheel alignment]
- Notice

Under-trays fitted obscuring some underside components
- Notice

Nearside rear brake slight bind
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Engine covers fitted obscuring some components in the engine bay

**MOT #8** 2014-03-12 13:28**MOT test number** 546581274031**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside rear outer door handle broken but still opens door
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Engine man/light on

MOT #7 2014-03-12 12:37**MOT test number** 299201474008**Result** ✗ Failed

- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Nearside rear outer door handle broken but still opens door
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Engine man/light on
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Under-trays fitted obscuring some underside components

MOT #6 2013-03-26 15:17**MOT test number** 487865383035**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #5** 2013-03-26 11:35**MOT test number** 169885983449**Result** ✗ Failed**Notice** Offside rear brake slight bind**Fail** Rear brake application uneven (3.7.B.2)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in offside rear tyre**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2012-03-14 12:06**MOT test number** 876884172010**Result** ✓ Passed**MOT #3** 2012-03-14 09:49**MOT test number** 217114672058**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2011-03-04 14:32**MOT test number** 308073461084**Result** ✓ Passed**MOT #1** 2010-03-16 10:11**MOT test number** 961915470073**Result** ✓ Passed**Advice** Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-29
Last registration	2023-07-14
Complete history	See info



Registration #1	2007-03-29	17 mi
Registration #2	2010-03-16	15.099 mi
Registration #3	2011-03-04	17.600 mi
Registration #4	2012-03-14	22.092 mi
Registration #5	2012-03-14	22.092 mi
Registration #6	2013-03-26	24.242 mi
Registration #7	2013-03-26	24.244 mi
Registration #8	2014-03-12	26.795 mi
Registration #9	2014-03-12	26.795 mi
Registration #10	2015-03-03	29.784 mi
Registration #11	2016-02-23	34.370 mi
Registration #12	2016-02-23	34.370 mi
Registration #13	2016-02-23	34.370 mi
Registration #14	2016-02-23	34.370 mi
Registration #15	2016-02-23	34.370 mi
Registration #16	2016-02-23	34.370 mi
Registration #17	2016-02-23	34.370 mi
Registration #18	2016-02-23	34.370 mi
Registration #19	2016-02-23	34.370 mi
Registration #20	2016-02-23	34.370 mi
Registration #21	2016-02-23	34.370 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1871 mm
Height	1695 mm
Length	4089 mm
Wheel base	2666 mm
Kerb weight	1370 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6

Number of axles	2
Engine number	5427411