



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SE
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-14
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-08-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	15
Total items failed	12

MOT #13	2022-08-30 14:43
MOT test number	209724274801
Result	✓ Passed
Next expiry date	2023-08-29

MOT #12	2021-11-09 17:42
MOT test number	703912667205
Result	✓ Passed

MOT #11	2020-08-07 13:52
MOT test number	937902643571
Result	✓ Passed

MOT #10	2019-03-14 15:58
MOT test number	735438037833
Result	✓ Passed

**Advice** Tyre worn close to legal limit/worn on edge o/s and n/s/f (5.2.3 (e))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2019-03-07 10:52

**MOT test number**

657324564967

**Result****✗ Failed**

- Advice** Tyre worn close to legal limit/worn on edge o/s and n/s/f (5.2.3 (e))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Exhaust has a major leak of exhaust gases centre box (6.1.2 (a))
- Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Exhaust silencer insecure tail pipe (8.1.1 (b) (i))
- Fail** Offside Rear Anti-roll bar ball joint excessively worn drop/link/post (5.3.4 (a) (i))

**MOT #8**

2018-02-23 16:47

**MOT test number**

487231902950

**Result****✓ Passed**

- Advice** Chip in windscreen outside of zone A
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)

**MOT #7**

2016-11-09 16:44

**MOT test number**

690273940912

**Result****✓ Passed**

**MOT #6** 2015-11-09 14:52**MOT test number** 262233794583**Result** ✓ Passed**Advice** Has a cut on n/s front tyre but not deep enough to cause any damage**MOT #5** 2014-10-30 16:19**MOT test number** 288333804397**Result** ✓ Passed**MOT #4** 2014-10-29 15:33**MOT test number** 727722104314**Result** ✗ Failed**Fail** Rear Tie bar/rod has excessive play in a pin/bush (2.4.G.2)**Fail** Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2014-04-16 17:10**MOT test number** 206156804147**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Both rear tyres sawtoothed on inside edges**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-04-18 16:24**MOT test number** 277758703103**Result** ✓ Passed



MOT #12013-04-18 11:19

MOT test number597298903198

Result

Failed

- Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice

Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail

Parking brake: efficiency below requirements (3.7.B.7)
- Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✕  
Untaxed

Tax expired:  
12 September 2021

✕  
MOT

Expired:  
29 August 2023

Tax status	Expired at 12 September
Days left	961 days too late
MOT expiry date	29 August 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-05-19
Last registration	2022-08-30
Complete history	<a href="#">See info</a>



Registration #1	2010-05-19	29 mi
Registration #2	2013-04-18	40.839 mi
Registration #3	2013-04-18	40.840 mi
Registration #4	2014-04-16	50.949 mi
Registration #5	2014-10-29	53.910 mi
Registration #6	2014-10-30	53.910 mi
Registration #7	2015-11-09	74.611 mi
Registration #8	2016-05-20	75.277 mi
Registration #9	2016-05-20	75.277 mi
Registration #10	2016-05-20	75.277 mi
Registration #11	2016-05-20	75.277 mi
Registration #12	2016-05-20	75.277 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2016-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	768432