




report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH DSIGN
Colour	White
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-08-06
Pictures	5
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-06
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-14
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	11
Total items failed	6

MOT #9	2023-08-03 08:48
MOT test number	259158596534
Result	✓ Passed
Next expiry date	2024-08-14

MOT #8	2023-08-03 08:48
MOT test number	978877096100
Result	✗ Failed
Pass with rectification	Exhaust system insecure forward most rear exhaust mounting bracket corroded off the exhaust pipe (6.1.2 (a))
Pass with rectification	Brake pad(s) worn down to wear indicator o/s and n/s front inners (1.1.13 (a) (i))

MOT #7	2022-08-02 05:01
MOT test number	509292971035
Result	✓ Passed

MOT #6	2022-08-02 04:59
MOT test number	190047128312
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases at the rear silencer mounting bracket (6.1.2 (a))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative light on (5.2.3 (h))
Fail	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #5** 2021-08-04 13:34**MOT test number** 360188789169**Result** ✓ Passed**Advice** Exhaust mounting defective back box front hanger broken away from pipe (6.1.2 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2021-08-04 09:44**MOT test number** 991228767117**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust mounting defective back box front hanger broken away from pipe (6.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-08-15 08:07**MOT test number** 623644265288**Result** ✓ Passed**MOT #2** 2019-06-08 11:38**MOT test number** 808404432902**Result** ✓ Passed



MOT #1	2018-05-30 09:40
MOT test number	369106161302
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	14 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-12
Last registration	2023-08-03
Complete history	See info



Registration #1	2015-06-12	20 mi
Registration #2	2018-05-30	19.884 mi
Registration #3	2019-06-08	22.588 mi
Registration #4	2020-08-15	26.016 mi
Registration #5	2021-08-04	27.869 mi
Registration #6	2021-08-04	27.869 mi
Registration #7	2023-08-03	27.869 mi
Registration #8	2023-08-03	27.869 mi
Registration #9	2023-08-03	27.869 mi
Registration #10	2023-08-03	27.869 mi
Registration #11	2023-08-03	27.869 mi
Registration #12	2023-08-03	27.869 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1496 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	B2080349442