





report date: 2024-03-29

General information

Make	CITROEN
Model	C-CROSSER HDI VTR PLUS
Colour	Black
Year of manufacture	2009
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	380 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	191 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history

Entry 1

Date 2021-12-01

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

2022-10-24 11:49

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT #15

MOT expiry date	2025-01-03
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	26
Total items failed	4

MOT #17	2024-01-04 15:49
MOT test number	269728873655
Result	✓ Passed
Next expiry date	2025-01-03

MOT #16		2024-01-03 14:55
MOT test	t number	845681398408
Result		🗙 Failed
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))	
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1

MOT test number	566866536375
Result	✓ Passed
MOT #14	2021-11-12 16:40
MOT test number	177678561185
Result	✓ Passed
Advice General under body rust	
Advice Under tray fitted	

CarCheck.co.uk page 3/14



report date: 2024-03-29

✓ Passed

MOT #13 2020-12-01 09:30

MOT test number 752388215542

Result
✓ Passed

MOT #12 2020-11-25 10:01

MOT test number 286289295991

Result X Failed

MAJOR Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11 2019-11-26 16:23

MOT test number 771480514672

Result ✓ Passed

MOT #10 2019-11-21 10:57

MOT test number 101413736084

Result X Failed

MAJOR Emission control equipment obviously defective pat fluid tank broken (8.2.2.1 (a))

MOT #9 2018-11-29 15:13

MOT test number 652723007859

552723507635

Advice Both front lower suspension joints boots condition poor

Result

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #8		2018-11-27 10:22
MOT test	number	551999256944
Result		★ Failed
Advice	Both front lower suspension joints boots condition poor	
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a))	
MAJOR	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR	Offside Front Position lamp not working (4.2.1 (a))	

MOT #7	2017-11-29 15:00
MOT test number	411747849221
Result	✓ Passed
Advice Both rear trailing arms front bushes split	

MOT #6	2016-11-23 12:21
MOT test number	137405229245
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29



MOT #4		2015-11-25 11:33
MOT test	number	929701584458
Result		✓ Passed
Advice	Rear child seats fitted to rear seats	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)	
Advice	Rear tyres slightly perished	
Advice	Offside Track rod end ball joint has slight play (2.2.B.1f)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)	

MOT #3	2014-12-01 09:53
MOT test number	606875834339
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 6/14



YF090VE report date: 2024-03-29

MOT #2 2013-11-20 15:51

MOT test number 918664423322

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-12-13 09:34

MOT test number 929408442310

Result ✓ Passed

CarCheck.co.uk page 7/14



YF090VE report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14




report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	MK MK
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-08-14
Last registration	2024-01-04
Complete history	See info



Registration #1	2009-08-14	15 mi
Registration #2	2012-12-13	27.266 mi
Registration #3	2013-11-20	33.041 mi
Registration #4	2014-12-01	46.261 mi
Registration #5	2015-11-25	59.114 mi
Registration #6	2016-11-22	71.146 mi
Registration #7	2016-11-23	71.148 mi
Registration #8	2017-11-29	82.609 mi
Registration #9	2018-11-27	94.924 mi
Registration #10	2018-11-29	94.925 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		10.700 es
Registration #18		11.777 es
Registration #19		11.777 46

More info >

CarCheck.co.uk page 13/14



YF090VE report date: 2024-03-29

			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ694028034

CarCheck.co.uk page 14/14