



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 625 LX L1 HDI
Colour	White
Year of manufacture	2015
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	60.1 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





MOT history

MOT expiry date	2024-05-04
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	23
Total items failed	0

MOT #9	2023-05-05 11:34
MOT test number	682777128699
Result	✓ Passed
Next expiry date	2024-05-04
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #8	2023-05-02 10:08
MOT test number	529165086130
Result	✗ Failed
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Horn not working (7.7 (a))
MAJOR	Front Bumper insecure (6.1.4 (a) (i))
MAJOR	Nearside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
MAJOR	Nearside Front Body component damaged and likely to cause injury (6.2.1 (a) (i))

**MOT #7** 2022-04-29 15:32**MOT test number** 939277626234**Result** ✓ Passed**MOT #6** 2022-04-27 09:53**MOT test number** 367797668496**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Spare wheel missing**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Spare wheel carrier insecure (6.1.5 (a))**MOT #5** 2021-03-20 10:55**MOT test number** 269806407468**Result** ✓ Passed**MOT #4** 2020-06-11 08:48**MOT test number** 569251062187**Result** ✓ Passed

**MOT #3** 2020-01-10 04:14**MOT test number** 337095461589**Result** ✓ Passed**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #2** 2019-02-13 12:02**MOT test number** 159197910390**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2018-02-26 10:22**MOT test number** 672650371494**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
4 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	4 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-02
Last registration	2023-05-05
Complete history	<a href="#">See info</a>



Registration #1	2015-03-02	12 mi
Registration #2	2018-02-26	58.811 mi
Registration #3	2019-02-13	75.802 mi
Registration #4	2020-01-10	87.304 mi
Registration #5	2020-06-11	87.434 mi
Registration #6	2020-06-11	87.434 mi
Registration #7	2020-06-11	87.434 mi
Registration #8	2020-06-11	87.434 mi
Registration #9	2020-06-11	87.434 mi
Registration #10	2020-06-11	87.434 mi

More info >



Safety ratings

NCAP rating	★★★★☆	▢
Adult	56%	
Children	74%	
Pedestrian	63%	
Safety systems	48%	
Overall rating	59%	
Video	<a href="#">see crash video</a>	

Dimensions & weight

Width	1810 mm
Height	1801 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1299 kg
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBEM0343990