



DSI8VXF

report date: 2024-03-29

General information

| | |
|---------------------|----------------------|
| Make | SUZUKI |
| Model | SWIFT SZ5 BOOSTERJET |
| Colour | Silver |
| Year of manufacture | 2018 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.0 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 111 BHP |
| Max. torque | 170 Nm at 2.000 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 114 g/km |
| CO2 label | C |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2023-03-27 |
| Pictures | 0 |
| Listing price | View report |

source: [carcraft.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-14 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-30 |
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #6 | 2024-03-27 13:15 |
| MOT test number | 210154232947 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-30 |

| | |
|-----------------|------------------|
| MOT #5 | 2023-03-31 08:07 |
| MOT test number | 709681788369 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #4 | 2023-03-30 09:43 |
| MOT test number | 647157225889 |

| | |
|--------|----------|
| Result | ✗ Failed |
|--------|----------|

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing 185/55/R16 (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



| | |
|-----------------|------------------|
| MOT #3 | 2022-11-08 11:17 |
| MOT test number | 479987822725 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #2 | 2021-11-17 16:20 |
| MOT test number | 191253158111 |
| Result | ✓ Passed |
| <div><div>Advice</div> Tyre slightly damaged/cracking or perishing n/s/f o/s/f n/s/r o/s/r tyres cracking on shoulders between treads (5.2.3 (d) (ii))</div> | |

| | |
|-----------------|------------------|
| MOT #1 | 2021-04-12 10:50 |
| MOT test number | 178771571396 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
30 March 2025

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 30 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|-------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

| | | |
|----------|--|--|
| Damage 1 | | |
| Date | | |
| Category | | |
| Type | | |
| Damage 2 | | |
| Date | | |
| Category | | |
| Type | | |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2018-05-31 |
| Last registration | 2024-03-27 |
| Complete history | See info |



| | | |
|-----------------|------------|----------|
| Registration #1 | 2018-05-31 | 10 mi |
| Registration #2 | 2021-04-12 | 4.340 mi |
| Registration #3 | 2021-11-17 | 4.968 mi |
| Registration #4 | 2022-11-08 | 6.823 mi |
| Registration #5 | | |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |
| Registration #9 | | |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 88% |
| Children | 75% |
| Pedestrian | 69% |
| Safety systems | 44% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1735 mm |
| Height | 1480 mm |
| Length | 3840 mm |
| Wheel base | 2450 mm |
| Kerb weight | 940 kg |
| Max. allowed weight | 1380 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 37 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | K10C-1108807 |