



NVIOHFU

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO ACTIVE
Colour	Red
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN

**MOT history**

MOT #16	2023-03-09 12:01
MOT test number	538302273890
Result	✓ Passed
Next expiry date	2024-03-11
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Back box deteriorated
Advice	Exhaust has a minor leak of exhaust gases flexi broke (6.1.2 (a))

MOT #15	2023-03-07 15:14
MOT test number	525433641555
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases flexi broke (6.1.2 (a))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
Advice	Back box deteriorated

MOT #14	2022-02-22 16:57
MOT test number	277470709126
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2021-03-12 14:06
MOT test number	918047083431
Result	✓ Passed



MOT #12	2021-03-10 15:24
MOT test number	424919552326
Result	✗ Failed
Fail	Horn not working (7.7 (a) (ii))

MOT #11	2020-05-27 13:28
MOT test number	440850018491
Result	✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-05-24 08:17
MOT test number	267516714320
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

MOT #9	2018-05-18 16:10
MOT test number	144314136191
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2018-05-18 08:41**MOT test number** 558560138096**Result** ✗ Failed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear Nail in tyre near sidewall**MOT #7** 2017-05-30 13:44**MOT test number** 531998905241**Result** ✓ Passed**Advice** Rear coil springs corroded**Advice** Offside Front tyre on 3mm**MOT #6** 2017-05-30 09:55**MOT test number** 109813529963**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front tyre on 3mm**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear coil springs corroded

**MOT #5** 2016-05-12 16:12**MOT test number** 152008997809**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)**Advice** Engine breather pipes split**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Bonnet handle broken off**MOT #4** 2016-05-12 09:12**MOT test number** 448356836393**Result** ✗ Failed**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine breather pipes split**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)**Advice** Bonnet handle broken off**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #3** 2015-05-30 11:40**MOT test number** 388130255113**Result** ✓ Passed**Advice** Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)



MOT #2	2014-05-21 14:21
MOT test number	988061744135
Result	✓ Passed

MOT #1	2013-05-16 10:13
MOT test number	718076133158
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-31
Last registration	2023-03-09
Complete history	See info



Registration #1	2010-05-31	11 mi
Registration #2	2013-05-16	11.743 mi
Registration #3	2014-05-21	16.066 mi
Registration #4	2015-05-30	24.236 mi
Registration #5	2016-05-12	32.136 mi
Registration #6	2016-05-12	32.136 mi
Registration #7	2017-05-30	41.089 mi
Registration #8	2017-05-30	41.090 mi
Registration #9	2018-05-18	45.987 mi
Registration #10	2019-05-20	51.277 mi
Registration #11	2019-05-20	51.277 mi
Registration #12	2019-05-20	51.277 mi
Registration #13	2019-05-20	51.277 mi
Registration #14	2019-05-20	51.277 mi
Registration #15	2019-05-20	51.277 mi
Registration #16	2019-05-20	51.277 mi
Registration #17	2019-05-20	51.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5839116