



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 16V
Colour	Blue
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-28
Pictures	4
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #17	2020-11-13 11:01
MOT test number	339612226938
Result	✓ Passed
Next expiry date	2021-11-12

MOT #16	2020-11-07 10:09
MOT test number	386505939381
Result	✗ Failed
MAJOR Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #15	2019-11-05 15:18
MOT test number	894316467570
Result	✓ Passed

MOT #14	2019-11-05 15:18
MOT test number	285020207350
Result	✗ Failed
Pass with rectification	Rear Direction indicator incorrect colour both (4.4.3 (a))
Pass with rectification	Windscreen washer not working (3.5 (a))

MOT #13	2018-11-05 14:47
MOT test number	477431586896
Result	✓ Passed

**MOT #12** 2018-11-05 10:27**MOT test number** 530693127835**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2017-10-30 09:51**MOT test number** 954068582553**Result** ✓ Passed**MOT #10** 2016-11-01 09:57**MOT test number** 329446621306**Result** ✓ Passed**MOT #9** 2015-11-06 16:36**MOT test number** 235220952028**Result** ✓ Passed**MOT #8** 2015-11-06 13:11**MOT test number** 634373048813**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Fuel system component leaking filter (7.2.3)**MOT #7** 2014-10-24 10:45**MOT test number** 128427794280**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-10-24 15:18**MOT test number** 608157893296**Result** ✓ Passed**MOT #5** 2013-10-24 09:43**MOT test number** 107127093282**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-10-25 12:35**MOT test number** 288419192264**Result** ✓ Passed**MOT #3** 2012-10-25 09:57**MOT test number** 876039692206**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #2** 2011-10-19 08:58**MOT test number** 777862391293**Result** ✓ Passed**MOT #1** 2010-11-09 10:21**MOT test number** 604453210342**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-11
Last registration	2020-11-13
Complete history	See info



Registration #1	2008-01-11	15 mi
Registration #2	2010-11-09	51.899 mi
Registration #3	2011-10-19	70.881 mi
Registration #4	2012-10-25	89.980 mi
Registration #5	2012-10-25	89.983 mi
Registration #6	2013-10-24	102.539 mi
Registration #7	2013-10-24	102.539 mi
Registration #8	2014-10-24	120.174 mi
Registration #9	2015-11-06	136.909 mi
Registration #10	2015-11-06	136.910 mi
Registration #11	2016-11-06	151.377 mi
Registration #12	2016-11-06	151.377 mi
Registration #13	2016-11-06	151.377 mi
Registration #14	2016-11-06	151.377 mi
Registration #15	2016-11-06	151.377 mi
Registration #16	2016-11-06	151.377 mi
Registration #17	2016-11-06	151.377 mi
Registration #18	2016-11-06	151.377 mi
Registration #19	2016-11-06	151.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17390132