



report date: 2024-03-28

## General information

|                     |                 |
|---------------------|-----------------|
| Make                | VAUXHALL        |
| Model               | VECTRA CLUB 16V |
| Colour              | Blue            |
| Year of manufacture | 2002            |
| Top speed           | 126 mph         |
| 0 - 60 mph          | 10.2 seconds    |
| Gearbox             | 5 speed Manual  |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 121 BHP             |
| Max. torque             | 166 Nm at 3.800 rpm |
| Engine capacity         | 1.796 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 26.2 mpg            |
| Consumption extra urban | 47.9 mpg            |
| Consumption combined    | 36.7 mpg            |
| CO2 emission            | 184 g/km            |
| CO2 label               | I                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-05                  |
| Pictures      | 7                           |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2022-12-20 |
| MOT pass rate      | 65 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 6          |
| Total advice items | 24         |
| Total items failed | 13         |

|                  |   |
|------------------|---|
| MOT #17          | 2021-12-21 14:26                            |
| MOT test number  | 609231995871                                |
| Result           | ✓ Passed                                    |
| Next expiry date | 2022-12-20                                  |
| Advice           | Under body corrosion exahust cover corroded |

|                 |  |
|-----------------|--|
| MOT #16         | 2021-12-20 17:44                                 |
| MOT test number | 865318616983                                     |
| Result          | ✗ Failed   |
| Advice          | Under body corrosion exahust cover corroded      |
| Fail            | Rear Brake pipe excessively damaged (1.1.11 (c)) |

|                 |  |
|-----------------|--|
| MOT #15         | 2016-10-18 09:57   |
| MOT test number | 940604952335   |
| Result          | ✓ Passed   |
| Advice          | Offside Front Tyre worn close to the legal limit (4.1.E.1) |

**MOT #14**

2016-10-13 11:01

**MOT test number**

121226604945

**Result****✗ Failed**

- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Exhaust system not adequately supported (7.1.1)
- Fail** Nearside Headlamp not working on main beam (1.7.5a)
- Fail** Offside Headlamp aim too low (1.8)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside rear brake binding (3.7.B.1)

**MOT #13**

2014-08-20 16:53

**MOT test number**

485272134266

**Result****✓ Passed**

- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Notice** Play in steering rack inner joint(s)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Exhaust corroded
- Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #12**

2014-08-20 16:53

**MOT test number**

329332234254

**Result****✗ Failed**

- Notice** Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)
- Notice** Exhaust corroded
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2013-06-21 09:47

**MOT test number**

327972973133

**Result****✓ Passed****MOT #10**

2012-07-10 09:55

**MOT test number**

499582092130

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9**

2011-07-14 13:35

**MOT test number**

295055491125

**Result****✓ Passed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2011-07-13 09:53**MOT test number** 315704991184**Result** ✗ Failed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**Fail** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**MOT #7** 2010-07-15 09:20**MOT test number** 882086090135**Result** ✓ Passed**MOT #6** 2009-07-13 13:38**MOT test number** 262154099129**Result** ✓ Passed**MOT #5** 2009-07-13 11:51**MOT test number** 921624499132**Result** ✗ Failed**Fail** Nearside Front coil spring incomplete (2.4.C.1a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2008-06-25 11:05**MOT test number** 720877378164**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-07-13 09:38**MOT test number** 771644397172**Result** ✓ Passed



|                         |   |
|-------------------------|---|
| MOT #2                  | 2007-07-13 09:38                                  |
| MOT test number         | 512854397107                                      |
| Result                  | ✗ Failed  |
| Pass with rectification | Rear Registration plate lamp not working (1.1.5c) |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2006-06-16 09:32 |
| MOT test number | 172187266116     |
| Result          | ✓ Passed         |



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 December 2021

✕  
MOT

Expired:  
20 December 2022

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 1 December 2021      |
| Days left        | 879 days too late               |
| MOT expiry date  | 20 December 2022                |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | I          |
| Single payment (12 months)              | £ 320,00,- |
| Single six month payment                | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|                |            |
|----------------|------------|
| XXXXXXXXXX     | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX     | XXXXXXXXXX |
| XXXXXX         | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX     | XXXXXXXXXX |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>FA02XTN</b> |
| Plate since          | 2024-03-28   |
| Current registration |  <b>FA02XTN</b> |
| Plate since          | 2024-03-28   |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2002-07-31               |
| Last registration          | 2021-12-21               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2002-07-31 | 13 mi      |
| Registration #2  | 2006-06-16 | 60.108 mi  |
| Registration #3  | 2007-07-13 | 64.228 mi  |
| Registration #4  | 2008-06-25 | 69.748 mi  |
| Registration #5  | 2009-07-13 | 73.746 mi  |
| Registration #6  | 2009-07-13 | 73.746 mi  |
| Registration #7  | 2010-07-15 | 78.341 mi  |
| Registration #8  | 2011-07-13 | 83.352 mi  |
| Registration #9  | 2011-07-14 | 83.370 mi  |
| Registration #10 | 2012-07-13 | 88.370 mi  |
| Registration #11 | 2013-07-13 | 93.370 mi  |
| Registration #12 | 2014-07-13 | 98.370 mi  |
| Registration #13 | 2015-07-13 | 103.370 mi |
| Registration #14 | 2016-07-13 | 108.370 mi |
| Registration #15 | 2017-07-13 | 113.370 mi |
| Registration #16 | 2018-07-13 | 118.370 mi |
| Registration #17 | 2021-12-21 | 123.370 mi |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 2036 mm |
| Height      | 1460 mm |
| Length      | 4596 mm |
| Wheel base  | 2700 mm |
| Kerb weight | 1357 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 61 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of axles    | 2                     |
| Engine number      | 20Z16712              |