



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D4 SE AWD
Colour	Gold
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-05-23
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	42
Total items failed	1

MOT #13	2024-04-09 14:28
MOT test number	753308442073
Result	✓ Passed
Next expiry date	2025-04-08
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #12	2024-04-08 14:19
MOT test number	707014217357
Result	✗ Failed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords heavily perished and split to cord (5.2.3 (d) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords heavily perished and split to cord (5.2.3 (d) (i))

MOT #11	2023-03-29 10:34
MOT test number	298749923225
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/50/vr18 (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2023-03-28 11:23

MOT test number

660325616777

Result**✗ Failed**

- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/50/vr18 (5.2.3 (e))

MOT #9

2022-04-05 09:35

MOT test number

102440424519

Result**✓ Passed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 235/50/ZR18 (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2021-04-26 10:40**MOT test number** 589643058853**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both nearside and offside on their inner faces (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both nearside and offside (5.2.3 (d) (ii))**MOT #7** 2020-05-14 08:57**MOT test number** 220896392731**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front cv boot leaking**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #6** 2019-04-01 10:52**MOT test number** 506292489672**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))

**MOT #5**

2019-04-01 10:17

MOT test number

643835121500

Result**✗ Failed**

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords x4 (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4

2018-03-26 11:32

MOT test number

714696813793

Result**✓ Passed**

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3

2017-03-13 11:23

MOT test number

828440826154

Result**✓ Passed**

Advice Front tyres perished

Advice Rear tyres slightly perished



MOT #2	2017-03-13 11:23
MOT test number	531691903283
Result	✗ Failed
Advice	Front tyres perished
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Rear tyres slightly perished

MOT #1	2016-04-04 12:53
MOT test number	787920916335
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-01-01
Current registration	XXXXXX
Plate since	2023-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-04-05
Last registration	2024-04-09
Complete history	See info



Registration #1	2013-04-05	17 mi
Registration #2	2016-04-04	16.011 mi
Registration #3	2017-03-13	19.849 mi
Registration #4	2017-03-13	19.849 mi
Registration #5	2018-03-26	23.722 mi
Registration #6	2019-04-01	26.873 mi
Registration #7	2019-04-01	26.873 mi
Registration #8	2020-05-14	28.530 mi
Registration #9	2020-05-14	28.530 mi
Registration #10	2020-05-14	28.530 mi
Registration #11	2020-05-14	28.530 mi
Registration #12	2020-05-14	28.530 mi
Registration #13	2020-05-14	28.530 mi
Registration #14	2020-05-14	28.530 mi
Registration #15	2020-05-14	28.530 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1851 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1277808