



RENAULT

HV11YTT


report date: 2024-03-29

General information

|                     |   |
|---------------------|---|
| Make                | RENAULT                                 |
| Model               | GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI |
| Colour              | Silver                                  |
| Year of manufacture | 2011                                    |
| Top speed           | 112 mph                                 |
| Gearbox             | 6 speed Manual                          |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 110 BHP             |
| Max. torque             | 240 Nm at 1.750 rpm |
| Engine capacity         | 1.461 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 48.7 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 128 g/km            |
| CO2 label               | D                   |





Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-12-15                  |
| Pictures      | 5                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-03                  |
| Pictures      | 11                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-09-18 |
| MOT pass rate      | 71 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 4          |
| Total advice items | 36         |
| Total items failed | 12         |

MOT #14 2023-09-19 12:00

MOT test number 577996824096

Result ✓ Passed

Next expiry date 2024-09-18

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #13 2022-05-31 11:10

MOT test number 770858727924

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear shock absorber corroded
- Advice** Offside Rear coil spring corroded
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12**

2022-05-27 13:53

**MOT test number**

906796959947

**Result****✗ Failed****Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear coil spring corroded**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Rear shock absorber corroded**MOT #11**

2021-05-28 10:30

**MOT test number**

731517386481

**Result****✓ Passed****Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #10**

2021-05-26 13:46

**MOT test number**

485725485817

**Result**

✗ Failed

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Minor**

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail**

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))

**Advice**

Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #9**

2020-11-25 16:11

**MOT test number**

268997967193

**Result**

✓ Passed

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2020-11-25 16:11

**MOT test number**

244656644238

**Result**

✗ Failed

**Pass with rectification**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification**

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Pass with rectification**

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #7**

2019-11-27 14:39

**MOT test number**

266740197839

**Result**

✓ Passed

**MOT #6** 2019-11-26 11:17**MOT test number** 100520498076**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Side repeater likely to become detached (4.4.1 (c) (ii))**MOT #5** 2018-11-27 15:35**MOT test number** 587341847588**Result** ✓ Passed**Advice** Nearside flasher repeater damaged but functional**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside mirror slightly damaged**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2017-11-29 10:23**MOT test number** 897026485456**Result** ✓ Passed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)



|                 |   |
|-----------------|---|
| MOT #3          | 2016-11-18 16:45  |
| MOT test number | 591078875600  |
| Result          | ✓ Passed  |
| Advice          | Offside Front Tyre worn close to the legal limit (4.1.E.1)  |
| Advice          | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2015-11-26 09:01 |
| MOT test number | 586081140757     |
| Result          | ✓ Passed         |

|                 |   |
|-----------------|---|
| MOT #1          | 2014-06-04 09:19  |
| MOT test number | 788865154129  |
| Result          | ✓ Passed  |
| Advice          | Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e) |



Tax & MOT check

X

Untaxed

Tax expired:  
31 December 2023

✓

MOT

Expires:  
18 September 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 31 December 2023     |
| Days left        | 121 days too late               |
| MOT expiry date  | 18 September 2024               |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

|                      |                 |
|----------------------|-----------------|
| Number of plates     | 1               |
| Current registration | <b>REDACTED</b> |
| Plate since          | 2019-03-29      |
| Current registration | <b>REDACTED</b> |
| Plate since          | 2019-03-29      |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

|                   |         |      |
|-------------------|---------|------|
| Finance company   | RENAULT | 2024 |
| Date of agreement | RENAULT | 2024 |
| Agreement type    | RENAULT | 2024 |
| Agreement term    | RENAULT | 2024 |
| Agreement number  | RENAULT | 2024 |
| Contact info      | RENAULT | 2024 |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2011-03-25               |
| Last registration          | 2023-09-19               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2011-03-25 | 27 mi      |
| Registration #2  | 2014-06-04 | 43.349 mi  |
| Registration #3  | 2015-11-26 | 61.626 mi  |
| Registration #4  | 2016-11-18 | 74.809 mi  |
| Registration #5  | 2017-11-29 | 85.783 mi  |
| Registration #6  | 2018-11-27 | 96.288 mi  |
| Registration #7  | 2019-11-26 | 108.076 mi |
| Registration #8  | 2019-11-27 | 108.076 mi |
| Registration #9  | 2020-11-25 | 116.428 mi |
| Registration #10 | 2020-11-25 | 116.428 mi |
| Registration #11 | 2020-11-25 | 116.428 mi |
| Registration #12 | 2020-11-25 | 116.428 mi |
| Registration #13 | 2020-11-25 | 116.428 mi |
| Registration #14 | 2020-11-25 | 116.428 mi |
| Registration #15 | 2020-11-25 | 116.428 mi |
| Registration #16 | 2020-11-25 | 116.428 mi |
| Registration #17 | 2020-11-25 | 116.428 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 91%                             |
| Children       | 76%                             |
| Pedestrian     | 42%                             |
| Safety systems | 99%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1478 mm |
| Height              | 1645 mm |
| Length              | 4560 mm |
| Wheel base          | 2770 mm |
| Kerb weight         | 1430 kg |
| Max. allowed weight | 2128 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | D190014 |