



AG09WUD

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Grey
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg



**MOT history**

MOT #12	2021-04-17 08:50
MOT test number	253386400458
Result	✓ Passed
Next expiry date	2022-04-16

MOT #11	2021-04-13 13:55
MOT test number	775071793149
Result	✗ Failed

- MAJOR** Offside Front Headlamp aim not tested (4.1.2 (b))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Central Front Registration plate missing (0.1 (a))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10	2019-08-08 13:58
MOT test number	620360135510
Result	✓ Passed

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2018-08-09 12:09
MOT test number	612849391078
Result	✓ Passed

**MOT #8** 2017-08-10 12:38**MOT test number** 241384635640**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2017-08-10 12:38**MOT test number** 358137838020**Result** ✗ Failed**Pass with rectification** Offside Front wheel bearing has excessive play (2.5.A.3c)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2016-07-27 13:43**MOT test number** 388251565416**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2015-07-23 12:28**MOT test number** 297314405229**Result** ✓ Passed**MOT #4** 2014-07-31 10:16**MOT test number** 395822414219**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #3	2013-07-31 14:01
MOT test number	626172713245
Result	✓ Passed

MOT #2	2013-07-31 09:43
MOT test number	626352613220
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Outer Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2012-07-31 11:43
MOT test number	448923012296
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AG09WUD
Plate since	2019-06-29
Current registration	 AG09WUD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-08-14
Last registration	2021-04-17
Complete history	See info



Registration #1	2009-08-14	15 mi
Registration #2	2012-07-31	34.186 mi
Registration #3	2013-07-31	46.488 mi
Registration #4	2013-07-31	46.488 mi
Registration #5	2014-07-31	59.669 mi
Registration #6	2015-07-23	72.327 mi
Registration #7	2016-07-27	100.821 mi
Registration #8	2019-05-29	151.277 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG 116680