



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN SE TDI DSG 140
Colour	Grey
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2

Date	2023-01-10
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-19
Pictures	23
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-06-06
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	40
Total items failed	5

MOT #17 2023-08-17 10:59

MOT test number 959618640914

Result ✗ Failed

Fail Front Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #16 2022-06-07 07:58

MOT test number 640521897000

Result ✓ Passed

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15 2021-11-10 08:44

MOT test number 836151787778

Result ✓ Passed

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #14**

2021-11-09 14:47

MOT test number

286212143863

Result**✗ Failed****Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2021-01-25 16:13

MOT test number

833095191038

Result**✓ Passed****Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12**

2021-01-25 14:35

MOT test number

882809187805

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #11** 2020-01-21 15:59**MOT test number** 189334130062**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #10 2019-04-29 09:08**MOT test number** 244799157435**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))

MOT #9 2018-05-04 13:56**MOT test number** 440549785419**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear (2.4.G.2)

MOT #8 2017-04-24 14:04**MOT test number** 951291584053**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Lower Front suspension has slight play in a track control arm inner bush (2.5.B.2b)

Advice Nearside Rear bump stop worn

**MOT #7** 2017-04-24 12:03**MOT test number** 927449063194**Result** ✗ Failed**Advice** Nearside Rear bump stop worn**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Front suspension has slight play in a track control arm inner bush (2.5.B.2b)**MOT #6** 2016-05-04 09:49**MOT test number** 212631362491**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit misshaped inner edge (4.1.E.1)**Advice** Front Bonded suspension unit deteriorated but can function as intended wishbones rear bushes splitting (2.4.F.3)**Advice** Offside Rear Tyre worn close to the legal limit misshaped inner edge (4.1.E.1)**MOT #5** 2015-04-17 14:07**MOT test number** 516627405112**Result** ✓ Passed**MOT #4** 2014-04-30 15:39**MOT test number** 108990324103**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Front discs slightly worn



MOT #3	2013-05-10 13:01
MOT test number	155250733146
Result	✓ Passed
MOT #2	2013-01-03 09:46
MOT test number	839163903066
Result	✓ Passed
MOT #1	2012-10-26 10:09
MOT test number	276150202339
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
30 August 2022

✕
MOT

Expired:
6 June 2023

Tax status	Expired at 30 August 2022
Days left	607 days too late
MOT expiry date	6 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KX59YVG
Plate since	2019-03-28
Current registration	 KX59YVG
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-01
Last registration	2023-08-17
Complete history	See info



Registration #1	2009-11-01	18 mi
Registration #2	2012-10-26	35.567 mi
Registration #3	2013-01-03	37.430 mi
Registration #4	2013-05-10	37.571 mi
Registration #5	2014-04-30	44.371 mi
Registration #6	2015-04-17	51.306 mi
Registration #7	2016-05-04	58.276 mi
Registration #8	2017-04-24	63.942 mi
Registration #9	2017-04-24	63.942 mi
Registration #10	2018-05-04	69.244 mi
Registration #11	2019-05-04	75.000 mi
Registration #12	2020-05-04	80.756 mi
Registration #13	2021-05-04	86.512 mi
Registration #14	2022-05-04	92.268 mi
Registration #15	2023-05-04	98.024 mi
Registration #16	2024-05-04	103.780 mi
Registration #17	2025-05-04	109.536 mi
Registration #18	2026-05-04	115.292 mi
Registration #19	2027-05-04	121.048 mi
Registration #20	2028-05-04	126.804 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BKD C66894