



report date: 2024-03-28

General information

|                     |                          |
|---------------------|--------------------------|
| Make                | CITROEN                  |
| Model               | XSARA HDI DESIRE PICASSO |
| Colour              | Silver                   |
| Year of manufacture | 2010                     |
| Top speed           | 109 mph                  |
| Gearbox             | 5 speed Manual           |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 89 BHP              |
| Max. torque             | 215 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.1 mpg            |
| Consumption extra urban | 67.3 mpg            |
| Consumption combined    | 56.5 mpg            |
| CO2 emission            | 130 g/km            |
| CO2 label               | D                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-07-01                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-06-28 |
| MOT pass rate      | 73 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 4          |
| Total advice items | 29         |
| Total items failed | 14         |

|                  |                  |
|------------------|------------------|
| MOT #15          | 2023-06-03 07:30 |
| MOT test number  | 647264052121     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-06-28       |

|                 |                  |
|-----------------|------------------|
| MOT #14         | 2022-06-29 13:44 |
| MOT test number | 706399444699     |
| Result          | ✓ Passed         |

**MOT #13**

2022-04-04 12:29

**MOT test number**

209215991204

**Result****✗ Failed**

- Fail** Rear Exhaust silencer insecure (8.1.1 (b) (i))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt both sides rear
- Fail** Seat belt anchorage prescribed area strength or continuity significantly reduced near side outer sill (7.1.1 (a) (i))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 185/65/15 (5.2.3 (d) (i))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Stop lamp(s) not working both rear (4.3.1 (a) (ii))
- Fail** Seat belt anchorage prescribed area strength or continuity significantly reduced off side outer sill (7.1.1 (a) (i))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #12**

2021-03-28 09:37

**MOT test number**

428013114608

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-03-28 09:37

**MOT test number**

820258825246

**Result****✗ Failed****Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #10**

2020-03-09 12:03

**MOT test number**

293060194790

**Result****✓ Passed****Advice** Offside Rear Outer Tyre slightly damaged wall has slight lump (5.2.3 (d) (ii))**Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))**MOT #9**

2019-03-01 13:20

**MOT test number**

572202926896

**Result****✓ Passed****Advice** Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive outer sill soft (7.1.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive outer sill soft (7.1.1 (a) (i))

**MOT #8**

2019-03-01 09:46

**MOT test number**

204194306793

**Result**

✗ Failed

**Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive outer sill soft (7.1.1 (a) (i))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive outer sill soft (7.1.1 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2018-03-14 13:00

**MOT test number**

592118830263

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6**

2018-03-14 10:04

**MOT test number**

621605656634

**Result**

✗ Failed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #5**

2017-03-21 11:11

**MOT test number**

625205851927

**Result**

✓ Passed

**MOT #4** 2016-03-24 15:03**MOT test number** 397635612235**Result** ✓ Passed**Advice** Stone cuts in all tyres**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-03-03 09:45**MOT test number** 136162765069**Result** ✓ Passed**MOT #2** 2014-03-14 11:48**MOT test number** 197513974026**Result** ✓ Passed**Notice** Oil leak**Notice** Front brakediscs wearing**MOT #1** 2013-03-11 12:23**MOT test number** 937820973011**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** All tyres perishing



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
28 June 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 July              |
| <b>Days left</b>        | 64                              |
| <b>MOT expiry date</b>  | 28 June 2024                    |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | D          |
| <b>Single payment (12 months)</b>              | £ 150,00,- |
| <b>Single six month payment</b>                | £ 82,50,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 157,50,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 10,000 |
| Auction value               | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  ***** |
| Plate since          | 2019-06-28  |
| Current registration |  ***** |
| Plate since          | 2019-06-28  |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2010-03-31               |
| Last registration          | 2023-06-03               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-03-31 | 20 mi     |
| Registration #2  | 2013-03-11 | 38.388 mi |
| Registration #3  | 2014-03-14 | 46.686 mi |
| Registration #4  | 2015-03-03 | 55.481 mi |
| Registration #5  | 2016-03-24 | 63.336 mi |
| Registration #6  | 2017-03-21 | 69.959 mi |
| Registration #7  | 2018-03-14 | 77.806 mi |
| Registration #8  | 2018-03-14 | 77.806 mi |
| Registration #9  | 2019-03-01 | 84.660 mi |
| Registration #10 | 2019-03-01 | 84.660 mi |
| Registration #11 | 2019-03-01 | 84.660 mi |
| Registration #12 | 2019-03-01 | 84.660 mi |
| Registration #13 | 2019-03-01 | 84.660 mi |
| Registration #14 | 2019-03-01 | 84.660 mi |
| Registration #15 | 2019-03-01 | 84.660 mi |
| Registration #16 | 2019-03-01 | 84.660 mi |
| Registration #17 | 2019-03-01 | 84.660 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 81%                             |
| Children       | 77%                             |
| Pedestrian     | 32%                             |
| Safety systems | 83%                             |
| Overall rating | 71%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1751 mm |
| Height              | 1637 mm |
| Length              | 4276 mm |
| Wheel base          | 2760 mm |
| Kerb weight         | 1300 kg |
| Max. allowed weight | 1850 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | JBBV0050008      |