



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX EDGE TDCI
Colour	Black
Year of manufacture	2010
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-02
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-01-22
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	27
Total items failed	3

## MOT #15 2024-01-17 10:28

MOT test number 124389234811

Result ✓ Passed

Next expiry date 2025-01-22

- Advice** Rear Tyre slightly damaged/cracking or perishing N/S+O/S (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded N/S+O/S (5.3.1 (b) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened N/S+O/S (5.3.3 (b) (i))
- Advice** Front Service brake fluctuating, but not excessively N/S+O/S (1.2.1 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

## MOT #14 2023-01-16 13:41

MOT test number 400790905983

Result ✓ Passed

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt osr nsr
- Advice** Rear Coil spring corroded at bottom (5.3.1 (b) (i))



<b>MOT #13</b>	2022-01-10 10:47
<b>MOT test number</b>	109647695157
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #12</b>	2022-01-10 10:47
<b>MOT test number</b>	254454570291
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

<b>MOT #11</b>	2021-01-06 12:30
<b>MOT test number</b>	637326927535
<b>Result</b>	✓ Passed
<b>Advice</b>	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt Central 3 & nearside rear
<b>Advice</b>	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))
<b>Minor</b>	Offside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
<b>Advice</b>	Offside Front Play in steering rack inner joint(s)

**MOT #10** 2021-01-06 12:30**MOT test number** 521196133238**Result** ✗ Failed**Minor** Offside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt Central 3 & nearside rear**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i))**MOT #9** 2020-01-15 12:14**MOT test number** 846332257187**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured offside and nearside (4.4.3 (a))**MOT #8** 2019-01-17 11:14**MOT test number** 602580968608**Result** ✓ Passed**MOT #7** 2018-01-11 09:53**MOT test number** 334033321817**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn low on edges**Advice** Nearside Front Tyre worn low on edges**Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2017-01-12 15:28**MOT test number** 699220937904**Result** ✓ Passed**MOT #5** 2017-01-12 10:22**MOT test number** 210936237892**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 225/50/17 (4.1.E.1)**MOT #4** 2016-01-14 09:01**MOT test number** 207337861104**Result** ✓ Passed**MOT #3** 2015-01-17 11:01**MOT test number** 446677915036**Result** ✓ Passed**MOT #2** 2014-01-11 11:18**MOT test number** 416611514018**Result** ✓ Passed**MOT #1** 2013-01-05 09:23**MOT test number** 898475403048**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
22 January 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	22 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-22
Last registration	2024-01-17
Complete history	<a href="#">See info</a>



Registration #1	2010-01-22	28 mi
Registration #2	2013-01-05	27.271 mi
Registration #3	2014-01-11	32.777 mi
Registration #4	2015-01-17	38.274 mi
Registration #5	2016-01-14	42.393 mi
Registration #6	2017-01-12	48.080 mi
Registration #7	2017-01-12	48.081 mi
Registration #8	2018-01-11	54.301 mi
Registration #9	2019-01-17	59.186 mi
Registration #10	2019-01-17	59.186 mi
Registration #11	2019-01-17	59.186 mi
Registration #12	2019-01-17	59.186 mi
Registration #13	2019-01-17	59.186 mi
Registration #14	2019-01-17	59.186 mi
Registration #15	2019-01-17	59.186 mi
Registration #16	2019-01-17	59.186 mi
Registration #17	2019-01-17	59.186 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Max. allowed weight	2505 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	9E15196