





General information

Make	MINI
Model	COOPER D
Colour	White
Year of manufacture	2012
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	А




Internet history	
Entry 2	
Date	2021-07-18
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1			
Date	2021-07-16		
Pictures	1		
Listing price	View report		



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #11	2023-08-08 11:26
MOT test number	345759468591
Result	✓ Passed
Next expiry date	2024-08-07
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Under trays fitted at time of test limiting visibility of components	

МОТ #10	2023-07-25 13:07
MOT test number	597922324018
Result	🗙 Failed
DANGEROUS Nearside Front Tyre has a lump, caused by separation or partial failu side wall (5.2.3 (d) (ii))	ire of its structure Outer
Advice Under trays fitted at time of test limiting visibility of components	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
DANGEROUS Offside Front Road wheel fractured Inner edge (5.2.2 (a))	



GF62FBZ
report date: 2024-03-28

MOT #9		2022-07-22 09:14
MOT test	number	868704054464
Result		🗸 Passed
Minor	Offside Windscreen wiper blade defective Split (3.4 (b) (i))	
Advice	Vehicle passed emissions yet no print out available as too clean for analyser to de	tect
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #8	2021-07-23 16:24
MOT test number	666328813243
Result	✓ Passed

MOT #7	2020-07-24 15:32	
MOT test	number 143954282794	
Result	✓ Passed	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice (i))		
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4	

МОТ #6	2019-07-03 12:09
MOT test number	128992352746
Result	🗸 Passed
Advice Tyre worn close to legal limit/worn on edge both sides fronts and rears (5.2.3 (e)))

MOT #5	2018-07-03 15:06
MOT test number	185604077486
Result	✓ Passed



GF62FBZ
report date: 2024-03-28

MOT #4		2017-12-30 12:31
MOT test	number	749397179080
Result		✓ Passed
Advice	Undertray fitted obscuring some components	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre wearing on outer edge	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front Tyre wearing on outer edge	

MOT #3	2017-12-30 10:54
MOT test number	966146692104
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Front Tyre wearing on outer edge	
Advice Undertray fitted obscuring some components	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively Aero b	blade (8.2.2)
Advice Nearside Front Tyre wearing on outer edge	

MOT #2	2017-01-06 10:23
MOT test number	159363318326
Result	✓ Passed
Advice Covers fitted to underside of vehicle	





MOT #1	2015-12-04 11:42
MOT test number	944427287999
Result	✓ Passed



Tax & MOT check

Tax due: 1 August 2024	√ Taxed	Expires: 7 August 2024	✓ MOT
Tax status			Valid until 1 August
Days left			95
MOT expiry date			7 August 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-08
Last registration	2023-08-08
Complete history	See info



Registration #1	2012-10-08	20 mi
Registration #2	2015-12-04	26.134 mi
Registration #3	2017-01-06	29.951 mi
Registration #4	2017-12-30	32.592 mi
Registration #5	2017-12-30	32.592 mi
Registration #6	2018-07-03	33.892 mi
Registration #7	2019-07-03	50.603 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Destates #10		
Registration #10		11.777 mi
Registration #10		01.000 est 01.000 est
-		01.000 est 01.000 est 01.000 est
Registration #11		01.000 est 01.000 est 01.000 est 01.000 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	70458310