





report date: 2024-03-28

### General information

Make	MAZDA
Model	CX-5 SPORT NAV PLUS
Colour	Grey
Year of manufacture	2019
Top speed	125 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque	213 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	38.2 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

### Entry 1


Date 2022-06-03

Pictures 29

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



DC190XB report date: 2024-03-28

MOT history

MOT expiry date	2025-04-26
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #4		2024-04-26 09:46
MOT test	number	682014357743
Result		✓ Passed
Next expi	ry date	2025-04-26
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.3 mm legal	limit is 1.6mm (5.2.3 (e))
Advice (ii))	Nearside Rear Brake disc worn, pitted or scored, but not seriously weake	ened corroded (1.1.14 (a)

MOT #3		2023-04-18 13:37
MOT test	number	611152885478
Result		✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken	ned (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



**MOT** #2

Advice

DC19OXB

report date: 2024-03-28

2023-04-18 12:10

MOT test number

Result

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #1** 2022-04-27 15:50

**MOT test number** 263826241127

CarCheck.co.uk page 4/11



DC19OXB report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	26 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
**************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-06-28
Last registration	2024-04-26
Complete history	See info



Registration #1	2019-06-28	21 mi
Registration #2	2022-04-27	11.562 mi
Registration #3		11,777 mi
Registration #4		71.777 es
Registration #5		71,777 es
Registration #6		D.777 es

More info >

page 10/11 CarCheck.co.uk



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Max. allowed weight	2020 kg

## Additional information

Number of seats	5
Number of axles	2
Engine number	PE 31312050

CarCheck.co.uk page 11/11