



report date: 2024-03-29

General information

Make	VOLVO
Model	S90 D4 R-DESIGN
Colour	Blue
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	2.8 mpg
CO2 emission	121 g/km
CO2 label	D





Internet history


Entry 4

Date	2024-04-03
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 3

Date	2022-02-12
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 2

Date	2022-02-06
Pictures	5
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-06
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #4	2023-11-08 08:28
MOT test number	184286484630
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #3	2023-11-07 14:57
MOT test number	351672410599
Result	✗ Failed
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #2	2022-11-02 11:36
MOT test number	395027658102
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2021-10-25 10:58
MOT test number	613006165257
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-11-09
Last registration	2023-11-08
Complete history	See info



Registration #1	2018-11-09	25 mi
Registration #2	2021-10-25	51.684 mi
Registration #3	2023-11-08	51.684 mi
Registration #4	2023-11-08	51.684 mi
Registration #5	2023-11-08	51.684 mi
Registration #6	2023-11-08	51.684 mi
Registration #7	2023-11-08	51.684 mi
Registration #8	2023-11-08	51.684 mi
Registration #9	2023-11-08	51.684 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1697 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2569754