



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TIGUAN ESCAPE TDI
Colour	Grey
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.8 mpg
CO2 emission	186 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-01-21
Pictures	18
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-10-31
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	39
Total items failed	7

MOT #15	2023-10-31 09:36
MOT test number	686568396111
Result	✓ Passed
Next expiry date	2024-10-31

MOT #14	2022-11-01 17:09
MOT test number	678922672849
Result	✓ Passed
Advice	Central Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2021-10-15 11:45
MOT test number	332923195793
Result	✓ Passed
Advice	Central Rear Exhaust mounting defective (6.1.2 (a))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front lower wishbone rear pin bushes both sides (5.3.4 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2020-10-27 11:22

**MOT test number**

431438778335

**Result**

✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm bushes (5.3.4 (a) (i))

**Advice** Rear Brake lining(s) wearing thin Could not assess condition of pads seem low have advised presenter (1.1.13 (a) (ii))

**Advice** Central Rear Exhaust mounting defective (6.1.2 (a))

**Advice** Front Tyre worn close to legal limit/worn on edge both front tyres (5.2.3 (e))

**MOT #11**

2019-10-26 09:57

**MOT test number**

151435613887

**Result**

✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Central Rear Exhaust mounting defective (6.1.2 (a))

**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated Both front. (5.3.4 (b) (i))

**MOT #10**

2018-10-31 13:07

**MOT test number**

809926993256

**Result**

✓ Passed

**Advice** Items removed from driver's view prior to test

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #9** 2018-10-31 13:07**MOT test number** 177532963960**Result** ✗ Failed**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Items removed from driver's view prior to test**MOT #8** 2017-12-05 15:40**MOT test number** 789656484526**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2016-12-10 12:55**MOT test number** 293641146749**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Child Seat fitted not allowing full inspection of adult belt



<b>MOT #6</b>	2015-11-25 16:48
<b>MOT test number</b>	416306879004
<b>Result</b>	✓ Passed
<b>Advice</b>	Under trays and engine covers fitted

<b>MOT #5</b>	2015-01-20 09:56
<b>MOT test number</b>	638530725061
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Notice</b>	O/s rear tyre worn on inner edge
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #4</b>	2014-02-03 12:08
<b>MOT test number</b>	868394134017
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #3</b>	2014-02-01 09:18
<b>MOT test number</b>	505132534022
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
<b>Fail</b>	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Notice</b>	Rear brake discs worn -grooved -pitted
<b>Fail</b>	Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
<b>Fail</b>	Rear brake application uneven (3.7.B.2)



MOT #2	2013-01-29 10:48
MOT test number	797799423092
Result	✓ Passed

MOT #1	2013-01-26 09:50
MOT test number	198926723089
Result	✗ Failed
Fail	Offside Rear coil spring incomplete (2.4.C.1a)
Fail	Rear brake application uneven (3.7.B.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-02-01
Last registration	2023-10-31
Complete history	<a href="#">See info</a>



Registration #1	2010-02-01	6 mi
Registration #2	2013-01-26	29.004 mi
Registration #3	2013-01-29	29.004 mi
Registration #4	2014-02-01	38.724 mi
Registration #5	2014-02-03	38.724 mi
Registration #6	2015-01-20	50.298 mi
Registration #7	2015-11-25	62.093 mi
Registration #8	2016-12-10	70.371 mi
Registration #9	2017-12-05	77.085 mi
Registration #10	2018-01-01	77.085 mi
Registration #11	2018-01-01	77.085 mi
Registration #12	2018-01-01	77.085 mi
Registration #13	2018-01-01	77.085 mi
Registration #14	2018-01-01	77.085 mi
Registration #15	2018-01-01	77.085 mi
Registration #16	2018-01-01	77.085 mi
Registration #17	2018-01-01	77.085 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4457 mm
Wheel base	2604 mm
Kerb weight	1604 kg
Max. allowed weight	2260 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CBA 710453